

Course No. 388-332

Group No. B23

EXPERIMENT NO. : 04

NAME OF THE EXPERIMENT : MANUFACTURING OF A
JACK BY USING LATHE, SHAPE,
MILLING AND DRILLING MACHINE

10/11/2023

DATE OF WORK : 11-01-2024

DATE OF REPORT : 21-01-2024

NAME	MD MANABIL RATHI
ROLL	101010101
SEM	3
BRANCH	Tool 1
DEPT	ME

OBJECTIVES:

(i) To introduce with lathe, shaper & milling drill machines. ✓

(ii) To operate the machine to produce the jack (machine component) ✓

APPARATUS: 1. a. 3 phase induction motor - 3HP

b. Motor rpm - 1430

c. Variable rpm 8

maximum rpm - 115

minimum rpm - 35

d. Total feed - 30

maximum feed - 2.8 mm

minimum feed - 0.05

These all are the specifications of a lathe machine. ✓

2. Shaper machine:

a) 3 phase induction motor

b) 60 strokes per minute ✓

3. Vertical milling machine:

a) 250 rpm ✓

4. Bench drilling machine ✓

Tools: 1. Lathe machine cutting tools

- a) lat turning
- b) lat drilling
- c) lat facing
- d) lat parting
- e) lat boring

2. Milling machine cutter

Swag 3. Amoring paper (for surface finish)

4. Slide calipers

5. End mill cutter

6. Tape and tape holder

Now, all the cutting tools are HSS ✓

WORKING MATERIAL:

A cylinder of 39 mm dia

Surface rough

material: MILD STEEL ✓

Inspected

EQUIPMENT SPECIFICATION: A brief description of the machine parts and different components are given below:

1. LATHE MACHINE: A lathe machine is a machine tool which spins a block of material to perform various operations such as turning, drilling, parting, facing etc. lat applied rotating motion to workplace to create an object which will be the replica of the desired object.

The major components are:

a. Bed: All lathes have a bed which is horizontal beam. The bed supports all major components of lathe. Beds have a large mass and are rigidly built usually from gray and nodular cast iron. Bed absorbs large amount of vibration due to machining operation. The top portion of the bed has two ways. One is hardened and machined for wear resistance. At the end of the bed there is 'Head stock' and the other end is called 'Tail stock'.

b. Carrriage: In its simplest form the carriage holds the tool bit and moves it longitudinally (turning) or perpendicularly (facing) under the control of the operator. The operator moves the carriage manually via handwheel or automatically via engaging the feed shaft with the carriage feed mechanism which is power assisted. The handwheels on the carriage and its related slides are usually lubricated in making reproducible cuts.

c. Head stock: The head stock houses the main spindle, speed change mechanism and change gear. The head stock is required to be made robust due to cutting forces are directly involved in it. The main spindle is in general hollow to allow the long bars through it.

d. tailstock:

The tailstock is a tool and is mounted opposite to head stock. The spindle does not rotate but can travel longitudinally under the action of lead screw and handwheel.

e. feed and lead screw:

A feed screw is a long driving shaft that allows a series of gears to drive the carriage wheel. Both the feedscrew and leadscrew are driven by either the change gears on an intermediate gear box called a quick change gear box.

The leadscrew will be manufactured to either imperial or metric standards and will need a conversion ratio to be introduced to create thread forms from different family.

f. chuck:

Chuck usually consists of three or four jaws. These jaw chucks generally have a geared scroll design that makes the jaw self centering. They are usually used to hold the round cross sectional objects. Other type of chuck is four jaw independent chuck. This chuck is used to hold non-circular cross sectional object.

Faceplate:

A workpiece may be bolted or screwed to a faceplate, a large flat disc that mounts to the spindle.

Mandrels:

Mandrels are placed inside hollow or tubular workpieces and used to hold workpieces that require machining on both ends or on either cylindrical surfaces. Some mandrels are mounted between the centres of the lathe.

A typical engine lathe components are -

- 1) Head stock
- 2) Tail stock
- 3) Spindle
- 4) Slideways
- 5) Tool post
- 6) Compound rest
- 7) Saddle
- 8) Power feed clutch
- 9) Feed rod
- 10) Bed
- 11) Lead screw
- 12) Half nut
- 13) Apron
- 14) Break clutch control
- 15) Rack
- 16) Motor driver
- 17) Gear box

2. Shaper machine: A brief discussion of shaper machine is given below -

A shaper machine is used to make straight cut on the workpiece. Here the job is fixedly kept and tool moves over it horizontally. The material removed by shaper machine is very low. So now in modern industries shaper machine is replaced by other machines. A shaper operates by moving a hardened cutting tool backward and forward across the workpiece. But cutting happens only during the forward stroke. So the time of forward stroke has to be large. A shaper machine can be classified into standard, dress cut, horizontal universal, vertical, geared, crank hydraulic and travelling head shaper.

3. Milling machine:

Milling is the machining process of using rotary cutters to remove material from workpiece advancing (or feeding) in a direction at an angle with the tool. It covers wide variety of different operations and machines. One scales from small individual parts to large heavy duty grand milling operations.

4. Drill Machine: A geared head drilling machine is used in this experiment. It has operated on three phase electric power and generally of more rugged construction than equivalently size belt driven units.

EXPERIMENTAL PROCEDURE:

a) For external parts:

For external parts all operations are done in lathe machine. Operation steps are given below:

1. Facing: 375 rpm

Feed 0.1 mm perpendicular to the rotational axis /

2. Turning: initial dia 32 mm

final dia 30 mm

230 rpm

Feed 0.05 mm

depth of cut 1 mm /

3. Turning: initial dia 30 mm

final dia 29 mm

230 rpm

Feed 0.05 mm

depth of cut 0.05 mm /

for 30 mm length

4. Drilling: 375 rpm
manual operation
8 mm dia drill bit
for 30 mm long hole ✓

5. Drilling: 375 rpm
manually operated
15 mm dia drill bit
for 30 mm long hole ✓

6. Boring: initial dia 15 mm
final dia 16 mm
depth of cut 0.5 mm
375 rpm
feed 0.05 mm
for 30 mm long ✓

7. Chamfering: 45° angle
375 rpm ✓

8. Surface finishing with file and amoring
paper.

9. Facing: 230 rpm
manually operated ✓

10. Facing the opposite face manually
at 230 rpm ✓

b) For internal part, for internal part machining use lathe machine, milling machine, shaper, slotting machine and tap.

d) Lathe machine operation:

1. Facing: 375 rpm

0.05 mm feed perpendicular to the rotational axis

2. Turning: 230 rpm

0.05 mm feed

initial dia 32 mm

final dia 30 mm

depth of cut 1 mm

total 45 mm long

3. Turning: 230 rpm

0.05 mm feed

initial dia 30 mm

final dia 28 mm

(tolerance ± 0.1 mm)

30 mm long

4. Chamfering: 45° angle

375 rpm

5. Surface finish with file and

emery paper at 375 rpm

6. Turning: 250 rpm
manually operated ✓

7. Facing at opposite side:
375 rpm
manually operated ✓

ii. Milling machine operation:

3. Slotting: with end mill cutter
10 mm dia

depth of cut 3 mm

2.5 mm cut at each step cross motion

250 rpm ✓

iii. Shaper machine operation:

1. Chamfering: 45° angle

60 stroke per minute ✓

iv. Drilling machine operation: Drill a hole with
5 mm dia drill bit ✓

v. Internal tap making:

manually operated

6 mm internal dia

There was 3 type of tap we used two of

them. But all 3 types are recommended to use

for better performance. ✓

SCHEMATIC DIAGRAM OF VARIOUS OPERATIONS:

1. FACING:




Figure 1: Facing operation in a lathe machine

2. TURNING:




Figure 2: Turning operation in a lathe machine

3. Drilling:





Fig. No.:

Figure: Drilling operation in lathe machine

4. Parting:



→ direction of rotating workpiece

cutting tool

cutting tool

Figure: Parting operation in lathe machine




seed piece

growing from the seed

seedling

growing from the seed



seedling


seedling

growing from the seed




seedling


1) Chamfering & Bore grinding




2) Drilling by drill machine




3) Reaming by reamer




4) Internal thread by tap



view of jack:



Side view (internal part)



Side view (external part)




Fig. 12: 3-D view of jack

operation?

A machine assembly Jack is produced in this experiment. In this experiment we also studied the operating procedure of lathe, milling, shaping and drilling by performing various operation.

Hydraulic jack increases mechanical advantage. Different feed rate and rpm were needed in machining process. When we cut roughly and quickly we use large feed and large depth of cut in low rpm. But due to quick machining a large amount of heat is generated. So, it is needed to keep the temperature moderate. To do so, we use cutting fluid beside that it vanishes away chip. The fluid is a mixture of oil and water so that only water will cause damage to the machine.

When we want smooth surface finish, we use small feed, small depth of cut and higher rpm. But it will take much more time. So, in general finish cut is done at last step.