

VCDS  
Windows Based VAG/VAS Emulator  
VCDS Version: Release 10.6.3 Data version: 20101206  
www.Ross-Tech.com

Dealer/Shop Name:  
Workshop Code: 000 00000

Self-Diagnosis Log  
Wednesday,27, April,2011,16:40:28:36838

VIN: WAUZZZ8EX3A284167 License Plate:  
Mileage: 171870km-106795mi Repair Order:

Chassis Type: 8E - Audi A4 B6/B7  
Scan: 01 02 03 08 09 0F 11 15 16 17 18 36 37 45 46 55 56 57 65 67  
69 75 76 77

VIN: WAUZZZ8EX3A284167 Mileage: 171870km/106795miles

-----  
Address 01: Engine Labels: 038-906-019-AVF.lbl  
Part No: 038 906 019 JT  
Component: 1,9l R4 EDC 0000SG 1572  
Coding: 00002  
Shop #: WSC 63351  
VCID: 72E0C64C1429  
WAUZZZ8EX3A284167 AUZ6Z0B0454745

1 Fault Found:  
17965 - Charge Pressure Control: Positive Deviation  
P1557 - 35-10 - - - Intermittent  
Readiness: 0 0 X X X

-----  
Address 03: ABS Brakes Labels: 8E0-614-517.lbl  
Part No: 8E0 614 517  
Component: ABS/ESP front 1729  
Coding: 04255  
Shop #: WSC 06435  
VCID: E5CA2D1055E7

No fault code found.

-----  
Address 08: Auto HVAC Labels: 8E0-820-043.lbl  
Part No: 8E0 820 043 J  
Component: A4 Klimaautomat 1116  
Coding: 00000  
Shop #: WSC 63351  
VCID: 2854E424E275

2 Faults Found:  
01810 - Actuating Motor for Temperature Flap; Right (V159)  
41-10 - Blocked or No Voltage - Intermittent  
00716 - Air recirculation Flap Positioning Motor (V113)  
41-10 - Blocked or No Voltage - Intermittent  
-----

VCDS  
Self-Diagnosis Log  
Wednesday,27, April,2011,16:40:28:36838  
Page 2

VIN: WAUZZZ8EX3A284167 License Plate:

Address 09: Cent. Elect. Labels: 8E0-907-279-8E2.lbl  
Part No: 8E0 907 279 E  
Component: int. Lastmodul RDW 0305  
Coding: 00101  
Shop #: WSC 63351  
VCID: 346C00542EBD

2 Faults Found:

01753 - Windshield Wiper Motor (V) Stage 1  
31-10 - Open or Short to Ground - Intermittent  
01754 - Windshield Wiper Motor (V) Stage 2  
31-10 - Open or Short to Ground - Intermittent

---

Address 15: Airbags Labels: 8E0-959-655-84.lbl  
Part No: 8E0 959 655 B  
Component: Airbag 8.4EP 2000  
Coding: 0010702  
Shop #: WSC 63351 000 00000  
VCID: 36683A5C38C1

No fault code found.

---

Address 16: Steering wheel Labels: 8E0-953-549.lbl  
Part No: 8E0 953 549 F  
Component: Lenksäulenmodul 0308  
Coding: 00012  
Shop #: WSC 63351  
VCID: 36683A5C38C1

No fault code found.

---

Address 17: Instruments Labels: 8E0-920-9xx-8E2.lbl  
Part No: 8E0 920 900 K  
Component: KOMBI+WEGFAHRS. RB4 D36  
Coding: 00000  
Shop #: WSC 02590  
VCID: 2C5C1834F68D  
WAUZZZ8EX3A284167 AUZ6Z0B0454745

No fault code found.

---

VCDS  
Self-Diagnosis Log  
Wednesday,27,April,2011,16:40:28:36838  
Page 3

VIN: WAUZZZ8EX3A284167 License Plate:

Address 46: Central Conv. Labels: 8E0-959-433-MIN.lbl  
Part No: 8E0 959 433 BA  
Component: Komfortgerát TA7 1310  
Coding: 06976  
Shop #: WSC 63351  
VCID: 71E2C940112F

Part No: 8E1959801B  
Component: Törsteuer.FS BRM 0002

Part No: 8E1959802B  
Component: Törsteuer.BF BRM 0002

No fault code found.

-----  
Address 56: Radio Labels: 8E0-035-1xx-56.lbl  
Part No: 8E0 035 152  
Component: chorus II GRO 0008  
Coding: 01202  
Shop #: WSC 63351  
VCID: DDBA05F07DB7

1 Fault Found:  
00856 - Radio Antenna  
36-00 - Open Circuit

-----  
Address 76: Park Assist Labels: 8Z0-919-283.lbl  
Part No: 8Z0 919 283 A  
Component: Parkingsyst. A4 RDW D09  
Coding: 00114  
Shop #: WSC 63351  
VCID: 438E53887B13

1 Fault Found:  
01546 - Sensor for Parking Aid; Rear Mid-Left (G204)  
31-00 - Open or Short to Ground

End -----