

Village Automotive Service

Service Estimate 19670

Name	Jillson, Carlos	Company		Created	09/08/15	Year	2000
Address	220 Wright St	Address 2		Time	12:24 PM	Make	DODGE
Home	Yellow Springs, OH 45387	V.I.N. #	1B3ES46C2YD507691	Promised		Model	NEON
Work	406-570-3163	Eng/Trans	2.0L/AT	Advisor	Administrato	Lic.#	GDQ 9826
Fax				Division	AR	Fleet#	
				PO#		C/U#	Green
				Page#	1 of 4	Hat#	

Job Description

Change oil & filter and perform maintenance inspection

Check tire condition and pressure. Inspect belts and hoses. Check all under hood fluid levels and top off as necessary. Adjust tire inflation as necessary. Check wiper blade condition. Check exterior light operation. Grease all available fittings if applicable. Test battery.

Line Total	39.84
.5 Hours Labor	8.00
Parts	31.84
Sublets	0.00

Battery tests

Coolant tests

Belts, hoses, fluids levels, lights, wipers

Tires measure

Tire pressure set to front rear

Part Number	Description	QTY	Each	Total
21348	Oil Filter	1	5.89	5.89
5W30 SERVICE PRO	Service Pro 5w30	5	4.99	24.95
	Fluid recycling fee		1.00	1.00

Install new battery

Includes removal of battery hold down and any other components required for access to battery. Clean terminal ends. Install new battery. Reinstall any components removed, including hold down. Retest system for proper operation.

Line Total	105.95
0 Hours Labor	0.00
Parts	105.95
Sublets	0.00

Part Number	Description	QTY	Each	Total
526RMF	Battery	1	105.95	105.95

Brake inspection

Complete visual inspection of brake system components. Includes remove wheels and check friction material thickness. Measure rotor thickness and runout. Measure drum diameter. Inspect brake hoses and lines. Inspect for caliper movement in both the piston and slides. Inspect for wheel cylinder leakage or damage. Inspect brake hardware for wear or damage. Inspect master cylinder and check fluid condition.

Line Total	47.15
.5 Hours Labor	47.15
Parts	0.00
Sublets	0.00

WARNING: Manufacturer requires wheel nuts be torqued within a 100 miles after wheel is reinstalled. Wheels can loosen after initial tightening. Failure to follow this instruction may result in serious injury to vehicle occupant(s).

Estimates are an approximate dollar amount based on anticipated job details. It is possible for unexpected complications to cause some deviation from estimated costs. If additional labor or parts are required to finish the job, you will be contacted immediately.

Estimate Total	
Supplies	\$49.11
Subtotal	\$1,747.83
Tax	\$117.51
Total	\$1,865.34

Village Automotive Service

Service Estimate 19670

Name	Jillson, Carlos	Company		Created	09/08/15	Year	2000
Address	220 Wright St	Address 2		Time	12:24 PM	Make	DODGE
Home	Yellow Springs, OH 45387	V.I.N. #	1B3ES46C2YD507691	Promised		Model	NEON
Work	406-570-3163	Eng/Trans	2.0L/AT	Advisor	Administrato	Lic.#	GDQ 9826
Fax				Division	AR	Fleet#	
				PO#		C/U#	Green
				Page#	2 of 4	Hat#	

Job Description

Drum brake reline service

Remove and install new brake shoes and drums. Clean and replace hardware as required. Adjust as necessary.

Line Total	324.29
1.7 Hours Labor	160.29
Parts	164.00
Sublets	0.00

WARNING: Manufacturer requires wheel nuts be torqued within a 100 miles after wheel is reinstalled. Wheels can loosen after initial tightening. Failure to follow this instruction may result in serious injury to vehicle occupant(s).

Part Number	Description	QTY	Each	Total
H7288	Brake hardware	1	22.08	22.08
SB2913	Drum	2	45.18	90.36
Z519R	Shoes	1	51.56	51.56

Complete brake fluid flush

Includes removal of all dirty old brake fluid cleaning brake fluid reservoir, installing new brake fluid and bleeding each wheel until all fluid is replaced.

Line Total	94.95
.8 Hours Labor	79.85
Parts	15.10
Sublets	0.00

Part Number	Description	QTY	Each	Total
DOT 3	DOT 3 Brake Fluid	1	15.10	15.10

Testing and Inspection

Time and resources required for system failure diagnosis.

Line Total	113.15
1.2 Hours Labor	113.15
Parts	0.00
Sublets	0.00

Drivers window diagnosis and panel removal and installation.

Install new Wiper Blades

Line Total	15.30
0 Hours Labor	0.00
Parts	15.30
Sublets	0.00

Part Number	Description	QTY	Each	Total
40519	Bosch Wiper Blade 19"	1	7.13	7.13
40522	Bosch Wiper Blade 22"	1	8.17	8.17

Mount and balance 2 tires

Dismount tire. Inspect/clean rim. Install new valve stem. Reinstall new tire to rim.

Line Total	145.90
.5 Hours Labor	0.00
Parts	145.90
Sublets	0.00

WARNING: Manufacturer requires wheel nuts be torqued within a 100 miles after wheel is reinstalled. Wheels can loosen after initial tightening. Failure to follow this instruction may result in serious injury to vehicle occupant(s).

Estimates are an approximate dollar amount based on anticipated job details. It is possible for unexpected complications to cause some deviation from estimated costs. If additional labor or parts are required to finish the job, you will be contacted immediately.

Estimate Total	
Supplies	\$49.11
Subtotal	\$1,747.83
Tax	\$117.51
Total	\$1,865.34

Village Automotive Service

Service Estimate 19670

Name	Jillson, Carlos	Company		Created	09/08/15	Year	2000
Address	220 Wright St	Address 2		Time	12:24 PM	Make	DODGE
Home	Yellow Springs, OH 45387	V.I.N. #	1B3ES46C2YD507691	Promised		Model	NEON
Work	406-570-3163	Eng/Trans	2.0L/AT	Advisor	Administrato	Lic.#	GDQ 9826
Fax				Division	AR	Fleet#	
				PO#		C/U#	Green
				Page#	3 of 4	Hat#	

Job Description

Part Number	Description	QTY	Each	Total
24515017	1856514 Milestar	2	67.95	135.90
VS	Valve stem	2	2.00	4.00
	Tire disposal		6.00	6.00

Wynns power steering flush

Include evacuation of all old power steering fluid and installation of Wynns power steering system flush chemicals. Cycling power steering system with steering wheel from steering lock to steering lock as to circulate flush chemical into all sections of power steering system. Removal of all flush chemical and installation of proper type power steering fluid per vehicle manufacture specifications.

Line Total	160.24
1 Hours Labor	94.29
Parts	65.95
Sublets	0.00

Part Number	Description	QTY	Each	Total
WYNNS 12	Power Steering Flush Kit	1	65.95	65.95

Labor to remove and replace lower ball joint(s)

Includes removal of wheel assembly and other components required for access to ball joint(s). Press ball joint/Remove ball joint from lower control arm. Clean/Inspect components for reinstallation. Press/Install new ball joint into control arm. Reassemble parts previously removed.

Line Total	562.00
4.4 Hours Labor	414.88
Parts	147.12
Sublets	0.00

WARNING: Manufacturer requires wheel nuts be torqued within a 100 miles after wheel is reinstalled. Wheels can loosen after initial tightening. Failure to follow this instruction may result in serious injury to vehicle occupant(s).

Part Number	Description	QTY	Each	Total
K7147	LOWER BALL JOINT	2	73.56	147.12

4 wheel alignment (front & rear)

Road test to check for drift, pull, & steering wheel position. Align to factory specification & print report. Re-road test. Re-check for drift and brake pull. Check for proper steering wheel position.

Line Total	89.95
1.5 Hours Labor	89.95
Parts	0.00
Sublets	0.00

Note: Front brake rotors rusted. Pad life 10mm

Muffler very rusty and brittle. Will need replaced soon.

Date	Service Due
------	-------------

Estimates are an approximate dollar amount based on anticipated job details. It is possible for unexpected complications to cause some diviation from estimated costs. If additional labor or parts are required to finish the job, you will be contacted immediately.

Estimate Total	
Supplies	\$49.11
Subtotal	\$1,747.83
Tax	\$117.51
Total	\$1,865.34

Village Automotive Service

Service Estimate 19670

Name	Jillson, Carlos	Company		Created	09/08/15	Year	2000
Address	220 Wright St	Address 2		Time	12:24 PM	Make	DODGE
Home	Yellow Springs, OH 45387	V.I.N. #	1B3ES46C2YD507691	Promised		Model	NEON
Work	406-570-3163	Eng/Trans	2.0L/AT	Advisor	Administrato	Lic.#	GDQ 9826
Fax				Division	AR	Fleet#	
				PO#		C/U#	Green
				Page#	4 of 4	Hat#	

Job Description

06/22/2016 Brake inspection

Estimates are an approximate dollar amount based on anticipated job details. It is possible for unexpected complications to cause some diviation from estimated costs. If additional labor or parts are required to finish the job, you will be contacted immediately.

Estimate Total	
Supplies	\$49.11
Subtotal	\$1,747.83
Tax	\$117.51
Total	\$1,865.34