




Recommended Services

Our technicians recommend the following services for your vehicle.

Original Customer Requests	Status	Cost	Deferred	Approved
1. 45 POINT INSPECTION INCLUDING BATTERY CHECK		\$0.00		X
replace front struts assemblies 4.0 (found front struts worn)	Fail			
code 0131 bank 1 sensor 1 (found check engine light)	Fail	\$475.70		
2. CLIENT DESCRIBED CONCERN. COOLANT FLUID FOUND UNDER HOOD. VEHICLE IS OVERHEATING. VTM-4 & CHECK ENGINE LIGHT IS ON. PLEASE ADVISE. .5 DIAGNOSIS APPROVED.		\$0.00		X
replace engine (Need motor replacement)		\$4,370.00		

Original Customer Requests	Status	Cost	Deferred	Approved
replace radiator 4.0 (found vehicle has no coolant in engine top tank leaking on radiator)	Fail	\$944.98		
Subtotal		\$5,790.68		
Inspection Recommendations	Status	Cost	Deferred	Approved
Replace oil pump gasket (Found engine oil leak)	Fail	\$1,529.05		
Ethanol Treatment (Based on manufacture standards regarding time and/or mileage of the vehicle and after checking available service history at our dealership, we recommend the following:)	Fail	\$25.95		
Perform power steering fluid exchange service (Based on manufacture standards regarding time and/or mileage of the vehicle and after checking available service history at our dealership, we recommend the following:)	Fail	\$149.95		See AI-2
Perform power steering system fluid exchange service (Found power steering fluid is excessively discolored)	Fail	\$149.95		See AI-2
Perform brake system fluid exchange (Found brake fluid is excessively discolored)	Fail	\$169.95		See AI-4
Perform alignment (Found steering component(s) excessively worn)	Fail	\$94.95		See AI-6
Perform four wheel alignment (Found strut mount(s) loose/worn/noisy)	Fail	\$94.95		See AI-6
Replace cabin air filter (Found cabin air filter excessively dirty)	Fail	\$65.95		See AI-15
Change engine oil and filter (Found engine oil excessively discolored/dirty)	Fail	\$40.41		See AI-18
Replace rear wiper blade insert (Found windshield wiper blade(s) worn)	Fail	\$15.00		See AI-19
Replace side engine mount (Found broken engine mount)	Fail	\$270.55		See AI-25
Replace front engine mount (Found broken engine mount)	Fail	\$578.47		See AI-25
Diagnose excessive coolant loss (Found coolant contaminated)	Fail	\$165.85		See AI-32
Replace water pump (Found engine coolant leak)	Fail	\$1,080.66		See AI-32
Diagnose check engine light (Found instrument cluster warning light illuminated)	Fail	\$29.95		See AI-36
Replace spark plugs (Based on manufacture standards regarding time and/or mileage of the vehicle and after checking available service history at our dealership, we recommend the following:)	Fail	\$309.00		See AI-37
Replace left outer tie-rod end (Found steering component(s) excessively worn)	Fail	\$266.58		See AI-39
Replace rack and pinion assembly (Found steering component(s) excessively worn, Found steering system leak)	Fail	\$1,627.07		See AI-52

Inspection Recommendations	Status	Cost	Deferred	Approved
Perform 90000 mile service (Based on manufacture standards regarding time and/or mileage of the vehicle and after checking available service history at our dealership, we recommend the following:)	Fail	\$823.00		See AI-54
Replace camshaft seal (Found engine oil leak)	Fail	\$242.36		See AI-55
Replace both rear shock absorbers (Found shock(s)/strut(s) leaking)	Fail	\$697.42		See AI-57
Replace both front struts (Found strut mount(s) loose/worn/noisy)	Fail	\$1,085.70		See AI-72
Replace air filter (Found air filter excessively dirty)	Fail	\$55.95		See AI-76
Replace both front sway-bar links (Found sway-bar bushing(s) excessively worn)	Fail	\$302.80		See AI-78
Replace front sway-bar bushings (Found sway-bar bushing(s) excessively worn)	Fail	\$311.30		See AI-78
Replace right front CV axle (Found CV joint(s) noisy/worn)	Fail	\$630.30		See AI-83
Replace left front CV axle (Found CV joint(s) noisy/worn)	Fail	\$630.30		See AI-83
Replace power steering pump (Found steering component(s) excessively worn, Found steering system leak)	Fail	\$775.97		See AI-84
Replace power steering belt (Found belt(s) excessively glazed)	Fail	\$95.18		See AI-87
Replace serpentine belt (Found belt(s) excessively glazed)	Fail	\$124.23		See AI-87
Replace both valve cover gaskets (Found engine oil leak)	Fail	\$745.48		See AI-91
Diagnose excessively low/contaminated/burnt transmission fluid (Found transmission fluid is excessively discolored)	Fail	\$109.95		See AI-98
Replace crankcase rear main seal (Found engine oil leak)	Fail	\$1,493.84		See AI-100
Replace radiator (Found engine coolant leak)	Fail	\$1,063.96		See AI-145
Perform transmission fluid exchange service (Based on manufacture standards regarding time and/or mileage of the vehicle and after checking available service history at our dealership, we recommend the following:)	Fail	\$127.95		See AI-158
Replace positive battery cable (Found battery cable/terminal excessively corroded)	Fail	\$315.15		See AI-159
Replace hood struts (Found hood strut(s) won't support hood)	Fail	\$205.95		See AI-198
Replace timing belt and water pump (Based on manufacture standards regarding time and/or mileage of the vehicle and after checking available service history at our dealership, we recommend the following:)	Fail	\$1,491.97		See AI-208
Subtotal		\$17,993.00		
Totals, Taxes and Fees		Cost	Deferred	Approved
Estimate Subtotal		\$23,783.68	\$0.00	\$0.00
Shop Fee		\$1,740.00		\$0.00
Tax		\$1,786.66		\$0.00

Totals, Taxes and Fees	Cost	Deferred	Approved
Estimate Total	\$27,310.34		\$0.00
<i>For "See AI-" items see the "Additional Information" section </i>			