

IDS-103.05A

Select Option

- Pass - FCDIM
- Pass - GPSM
- Pass - HCM
- Pass - IPC
- Pass - PAM
- Pass - PCM
- Pass - RCM
- Pass - SASM
- U0252:00-0A- BCMii
- U2101:00-0A- BCMii**

Optional equipment Modules

- Fail - AHCM
- Fail - IPM-A
- Fail - IPM-B

Body Control Module

Description - U2101
Control Module Configuration Incompatible

Failure Type - 00
No Additional Failure Type Information for this DTC

Status - 0A (Current DTC)
Fault is currently present.

Diagnostic Protocol - 14229
Select I button help for additional information on 14229 DTC structure

13:28
24/01/2017

IDS-103.05A

Select Option

- Pass - RCM
- Pass - PAM
- Pass - RCM
- Pass - SASM
- B10AC:4A-0A- BCMii
- B112B:07-0A- BCMii
- U0252:00-0A- BCMii
- U2101:00-0A- BCMii
- U0073:88-2C- IPC
- U0159:00-2E- IPC
- P0148:00-28- PCM
- P0564:82-2E- PCM**
- P2539:00-28- PCM

Snapshot Data

- U0073:88-2C- IPC

Powertrain Control Module

Description - P0564
Cruise Control Multi-function Input A Circuit

Failure Type - 82
Alive/Sequence Counter Incorrect/Not Updated

Status - 2E (Current DTC)
Fault is currently present.

Diagnostic Protocol - 14229
Select I button help for additional information on 14229 DTC structure

13:26
24/01/2017

IDS-103.05A

 

Select Option

- Pass - GPSM
- Pass - HCM
- Pass - PAM
- Pass - RCM
- Pass - SASM
- B10AC:4A-0A- BCMii
- B112B:07-0A- BCMii**
- U0252:00-0A- BCMii
- U2101:00-0A- BCMii
- U0073:88-2C- IPC
- U0159:00-2E- IPC
- P0148:00-28- PCM
- P0564:82-2E- PCM
- P2539:00-28- PCM

Body Control Module

Description - B112B
Steering Wheel Module

Failure Type - 07
Mechanical Failures

Status - 0A (Current DTC)
Fault is currently present.

Diagnostic Protocol - 14229
Select **I** button help for additional information on 14229 DTC structure







13:25
24/01/2017

IDS-103.05A

Select Option

- Pass - GPSM
- Pass - HCM
- Pass - PAM
- Pass - RCM
- Pass - SASM
- B10AC:4A-0A- BCMii**
- B112B:07-0A- BCMii
- U0252:00-0A- BCMii
- U2101:00-0A- BCMii
- U0073:88-2C- IPC
- U0159:00-2E- IPC
- P0148:00-28- PCM
- P0564:82-2E- PCM
- P2539:00-28- PCM

Body Control Module

Description - B10AC
Cruise Control Switch

Failure Type - 4A
Incorrect Component Installed

Status - 0A (Current DTC)
Fault is currently present.

Diagnostic Protocol - 14229
Select I button help for additional information on 14229 DTC structure

13:25
24/01/2017