



Vacuum Casting Procedures



Please check <https://www.3erp.com> for more about vacuum casting.



Step 1: SLA Master



Step 2: Pour rubber



Step 3: Cast urethane



Step 4: Autoclave



Step 5: Demold part



Step 6: Clean flash off part