Condition Report

Completed by Alliance Inspection Management

2013 Mercedes-Benz CLS-Class

VIN: WDDLJ7EB8DA064242

Vehicle Information

Year :	2013
Brand :	Mercedes-Benz
Model :	CLS-Class
Series :	CLS63 AMG
Body Type :	Sedan
Drive Type :	RWD
Engine :	5.5L, 8, Gas
Transmission :	7-Speed A/T
Mileage :	15066
Exterior Color :	Silver
Trim Color :	Black
Trim Type :	Leather

Inspection Details

Inspection Date :	05 Feb 2014 12:04 PM
Inspection ID :	415733
Inspector :	4491
Grade :	A

Inspection Notes : 6 point undercarriage inspection completed. Engine Cradle ok.
Twin-Turbocharged Tire_Loc=Spare MFR=Vredestein

Vehicle Accessories

- A/C
- Air Conditioner
- Anti Lock Braking System
- Bucket Seats
- Cruise Control
- Dual Front Zone Automatic Temp Control
- Heated Front Seats
- Intermittent Wipers
- Leather Steering Wheel
- Pass-Through Rear Seat
- Power Locks
- Power Windows
- Rear Parking Aid
- Satellite Radio
- Tire Pressure Monitor
- Trip Computer
- Ventilated Leather Trimmed Net Seats
- Xm Satellite Radio
- ABS
- Air Suspension
- Automatic On/Off Headlights
- CD Changer
- Curtain\Side Airbags
- Dual Zone Automatic Temp Control
- Heated Mirrors
- Keyless Start
- MP3 Player
- Passenger Air Bag
- Power Moonroof / Sunroof
- Premium Sound System
- Rear Sonar System
- Side Airbags
- Tires - Front Performance
- Turbocharged
- Video DVD Player
- Adjustable Steering Wheel
- Alloy Wheels
- Bluetooth
- CD Player
- Daytime Running Lights
- Engine Immobilizer
- Integrated Turn Signal Mirrors
- Leather Seats
- Mirror Memory
- Power Bucket Seats
- Power Seat W/Memory
- Rear Bench Seat
- Rear Spoiler
- Sirius Satellite Radio
- Tires - Rear Performance
- Underbody Spoilers
- Wheel Locks
- Advanced Climate Control
- Aluminum Wheels
- Brake Assist
- Climate Control
- Driver Air Bag
- Floor Mats
- Intelligent Key
- Leather Seats (3rd Row Is Vinyl)
- Navigation System
- Power Door Locks
- Power Steering
- Rear Head Air Bag
- Rearview Monitor
- Sun/Moon Roof
- Traction Control
- Vehicle Dynamic Control
- Xenon Headlamps

Tire Information

	Manufacturer	Size	Depth		Manufacturer	Size	Depth
Left Front :	Continental	255/35-19	8/32	Right Front :	Continental	255/35-19	8/32
Left Rear :	Continental	285/30-19	8/32	Right Rear :	Continental	285/30-19	8/32
Spare :	Other	175/80-19	4/32				

*Tire Depth of 5/32 or greater is considered normal

Vehicle Condition

Wear and Tear

1	Front Bumper Cover	Chipped	1

Condition Report

Completed by Alliance Inspection Management

Alliance Inspection Management

2013 Mercedes-Benz CLS-Class

VIN: WDDLJ7EB8DA064242

One chip 1/4" diameter in center of bumper.

Vehicle Inspection Points

Legend: ● **Item inspected and is ok** ● **Item inspected and contains an issue** ❍ **Item is not present or could not be inspected**

Exterior

Vehicle Identification Number On Door Jam	●	Vehicle Identification Number On Dashboard	●
Front Lamps	●	Rear Lamps	●
Side Marker	●	Frame / Unibody	●
Roof Rack	❍	Door And Side Moldings	●
Wiper Blades/Arms	●	Check Engine Compartment for Fluid Leaks	●
Check Transmission For Leaks	●	Battery	●
Fluid Levels	●	Belts/Hoses	●
Emission Sticker	●		

Interior

Power Door Locks	●	Alarm	●
Back up Camera	●	Navigation/Entertainment System	❍
Owners Manual	●	CD/DVD	●
Radio/Speakers	●	Cooled/Heated Seats	●
AC/Heater	●	Trunk Release	●
Tilt Steering Column Functions	●	Parking Brake	●
Dome Light	●	Knobs, Buttons and Other Controls	●
Horn Functions	●	Hood Release	●
Hazard Lights	●	Power Mirrors	●
Power Seats	●	Power Sunroof	●
Seatbelts	●	Power Windows	●
Carpet - Front	●	Warning Lights	●
Headliner Condition	●	Convertible Top Operational	❍
Interior Trim	●	Cargo Area Carpet	●
First Aid Kit If Applicable	●	Spare Tire	●
Tailgate Closing Assist	●	Toolkit Complete	●
Carpet - Rear	●		

Date : 05 Feb 2014

Signature : _____

V1.3B2B

Condition Report

Completed by Alliance Inspection Management

2013 Mercedes-Benz CLS-Class

VIN: WDDLJ7EB8DA064242

Vehicle Pictures

Picture Description : **Other**

Picture Description : **Other**

Picture Description : **Other**

Picture Description : **Other**

Picture Description : **Cargo Area**

Picture Description : **Odometer**

Condition Report

Completed by Alliance Inspection Management

2013 Mercedes-Benz CLS-Class

VIN: WDDLJ7EB8DA064242

Picture Description : **Dashboard**

Picture Description : **Right Rear Corner**

Picture Description : **Wheel**

Picture Description : **Other**

Picture Description : **Odometer**

Picture Description : **Left Front Corner**

Condition Report

Completed by Alliance Inspection Management

2013 Mercedes-Benz CLS-Class

VIN: WDDLJ7EB8DA064242

Picture Description : **Front Interior**

Picture Description : **Wheel**

Picture Description : **Other**

Picture Description : **Other**

Picture Description : **Wheel**

Picture Description : **Wheel**



Condition Report

Completed by Alliance Inspection Management

2013 Mercedes-Benz CLS-Class

VIN: WDDLJ7EB8DA064242

Picture Description : **VIN**

Picture Description : **Other**

Picture Description : **Other**



Picture Description : **Wheel**

Picture Description : **Left Front Corner**

Picture Description : **Other**

Condition Report

Completed by Alliance Inspection Management

2013 Mercedes-Benz CLS-Class

VIN: WDDLJ7EB8DA064242

Picture Description : **Other**

Condition Report

Completed by Alliance Inspection Management

2013 Mercedes-Benz CLS-Class

VIN: WDDLJ7EB8DA064242

Damage Pictures

Picture Description : **No Picture**