

Condition Report

Completed by Alliance Inspection Management



2009 Nissan GT-R

VIN: JN1AR54F09M252040



Vehicle Information

Year : 2009
Brand : Nissan
Model : GT-R
Series : Premium
Body Type : Coupe
Drive Type : AWD
Engine : 3.8L, 6, Gas
Transmission : 6-Speed A/T
Mileage : 33127
Exterior Color : Silver
Trim Color : Grey
Trim Type : Leather

Inspection Details

Inspection Date : 14 Mar 2014 1:12 PM
Inspection ID : 430520
Inspector : 4490
Grade : C

Inspection Notes :

"SIX (6) POINT UNDERCARRIAGE INSPECTION PERFORMED. ENGINE CRADLE OK."
prior repair is good paint work.

Vehicle Accessories

- A/C
- Air Conditioner
- Automatic On/Off Headlights
- CD Player
- Driver Air Bag
- Front Side Airbags
- Keyless Start
- Navigation System
- Power Driver Seat
- Power Passenger Seat
- Rear Head Air Bag
- Tires - Front Performance
- Xenon Headlamps
- ABS
- Alloy Wheels
- Bluetooth
- Climate Control
- Dual Front Zone Automatic Temp Control
- Heated Front Seats
- Leather Seats
- Paddle Shifters
- Power Front Seat
- Power Steering
- Satellite Radio
- Tires - Rear Performance
- Xm Satellite Radio
- AM/FM Stereo
- Aluminum Wheels
- Bose Audio
- Cruise Control
- Engine Immobilizer
- Heated Mirrors
- Leather Steering Wheel
- Passenger Air Bag
- Power Hatch
- Power Windows
- Side Airbags
- Traction Control
- Adjustable Steering Wheel
- Anti Lock Braking System
- Bucket Seats
- Curtain\Side Airbags
- Front Reading Lamps
- Intermittent Wipers
- MP3 Player
- Power Door Locks
- Power Locks
- Premium Sound System
- Tire Pressure Monitor
- Turbocharged

Tire Information

	Manufacturer	Size	Depth		Manufacturer	Size	Depth
Left Front :	Michelin	275/35-20	9/32	Right Front :	Michelin	275/35-20	9/32
Left Rear :	Bridgestone	285/35-20	4/32	Right Rear :	Bridgestone	285/35-20	4/32
Spare :		Tire Does Not Exist		*Tire Depth of 5/32 or greater is considered normal			

Vehicle Condition

Wear and Tear

1	Left Front Seat	Worn	Acceptable
2	Hood	Prev Repair	Acceptable
3	Right Front Fender	Prev Repair	Acceptable
4	Front Bumper Cover	Prev Repair	Acceptable

Condition Report

Completed by Alliance Inspection Management



2009 Nissan GT-R

VIN: JN1AR54F09M252040

5	Left Front Fender	Prev Repair	Acceptable
6	Left Front Door	Prev Repair	Acceptable
7	Left Qtr Panel	Prev Repair	Acceptable
8	Rear Bumper Cover	Scratch Light	2" to 3"
9	Left Rear Bumper Cover	Dent/Paint Dmg	2" to 3"

Vehicle Inspection Points

Legend: ● Item inspected and is ok ● Item inspected and contains an issue ○ Item is not present or could not be inspected

Exterior

Vehicle Identification Number On Door Jam	●	Vehicle Identification Number On Dashboard	●
Front Lamps	●	Rear Lamps	●
Side Marker	●	Frame / Unibody	●
Roof Rack	○	Door And Side Moldings	●
Wiper Blades/Arms	●	Check Engine Compartment for Fluid Leaks	●
Check Transmission For Leaks	●	Battery	●
Fluid Levels	●	Belts/Hoses	●
Emission Sticker	●		

Interior

Power Door Locks	●	Alarm	●
Back up Camera	○	Navigation/Entertainment System	●
Owners Manual	●	CD/DVD	●
Radio/Speakers	●	Cooled/Heated Seats	●
AC/Heater	●	Trunk Release	●
Tilt Steering Column Functions	●	Parking Brake	●
Dome Light	●	Knobs, Buttons and Other Controls	●
Horn Functions	●	Hood Release	●
Hazard Lights	●	Power Mirrors	●
Power Seats	●	Power Sunroof	○
Seatbelts	●	Power Windows	●
Carpet - Front	●	Warning Lights	●
Headliner Condition	●	Convertible Top Operational	○
Interior Trim	●	Cargo Area Carpet	●
First Aid Kit If Applicable	○	Spare Tire	●
Tailgate Closing Assist	○	Toolkit Complete	●
Carpet - Rear	●		

Condition Report

Completed by Alliance Inspection Management



2009 Nissan GT-R

VIN: JN1AR54F09M252040

Date : 14 Mar 2014

Signature : _____

V1.3B2B

Condition Report

Completed by Alliance Inspection Management

2009 Nissan GT-R

VIN: JN1AR54F09M252040

Vehicle Pictures

Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Wheel**



Picture Description : **Other**



Condition Report

Completed by Alliance Inspection Management


2009 Nissan GT-R

VIN: JN1AR54F09M252040

Picture Description : **Wheel**



Picture Description : **VIN**



Picture Description : **Other**



Picture Description : **Wheel**



Picture Description : **Dashboard**



Picture Description : **Other**



Condition Report

Completed by Alliance Inspection Management

2009 Nissan GT-R

VIN: JN1AR54F09M252040

Picture Description : **Other**



Picture Description : **Dashboard**



Picture Description : **Front Interior**



Picture Description : **Wheel**



Picture Description : **Other**



Picture Description : **Other**



Condition Report

Completed by Alliance Inspection Management

2009 Nissan GT-R

VIN: JN1AR54F09M252040

Picture Description : **Right Rear Corner**



Picture Description : **Cargo Area**



Picture Description : **Odometer**



Picture Description : **Left Front Corner**



Condition Report

Completed by Alliance Inspection Management

2009 Nissan GT-R

VIN: JN1AR54F09M252040

Damage Pictures

Picture Description : **Seat Worn Acceptable**



Picture Description : **Qtr Panel Prev Repair Acceptable**



Picture Description : **Fender Prev Repair Acceptable**



Picture Description : **Bumper Cover Dent/Paint Dmg 2" to 3"**



Picture Description : **Hood Prev Repair Acceptable**



Picture Description : **Fender Prev Repair Acceptable**



Condition Report

Completed by Alliance Inspection Management

2009 Nissan GT-R

VIN: JN1AR54F09M252040

Picture Description : **Bumper Cover Dent/Paint Dmg 2" to 3"**



Picture Description : **Door Prev Repair Acceptable**



Picture Description : **Seat Worn Acceptable**



Picture Description : **Bumper Cover Prev Repair Acceptable**

