

Condition Report

Completed by Alliance Inspection Management

2007 Porsche 911

VIN: WP0CA29937S765208



Vehicle Information

Year : 2007
Brand : Porsche
Model : 911
Series :
Body Type : Convertible
Drive Type : RWD
Engine : 3.6L, 6, Gas
Transmission : Tiptronic
Mileage : 28650
Exterior Color : White
Trim Color : Tan
Trim Type : Leather

Inspection Details

Inspection Date : 18 Apr 2014 1:51 PM
Inspection ID : 448498
Inspector : 3661

Grade : A

Inspection Notes : 2007 Porsche 911 in great condition. Interior carpet has no stains, leather has no tears with exception of driver seat having tear less than 1/2", Seller is having driver seat repaired today. Hard top included. Minor bug damage on front bumper. No dents or scratches on exterior. Vehicle brakes work while moving vehicle forward and reverse transmission shifts properly.

Vehicle Accessories

- A/C
- Aluminum Wheels
- Cruise Control
- Leather Seats
- Passenger Air Bag
- Power Steering
- Rear Parking Aid
- Tires - Rear Performance
- ABS
- Bucket Seats
- Driver Air Bag
- Leather Steering Wheel
- Power Door Locks
- Power Windows
- Rear Spoiler
- Traction Control
- AM/FM Stereo
- CD Player
- Heated Mirrors
- MP3 Player
- Power Driver Seat
- Premium Sound System
- Tire Pressure Monitor
- Adjustable Steering Wheel
- Climate Control
- Intermittent Wipers
- Pass-Through Rear Seat
- Power Passenger Seat
- Rear Bench Seat
- Tires - Front Performance

Tire Information

| | Manufacturer | Size | Depth | | Manufacturer | Size | Depth |
|--------------|---------------------|-----------|-------|---|--------------|-----------|-------|
| Left Front : | Michelin | 235/35-19 | 6/32 | Right Front : | Michelin | 235/35-19 | 6/32 |
| Left Rear : | Michelin | 295/30-19 | 8/32 | Right Rear : | Michelin | 295/30-19 | 8/32 |
| Spare : | Tire Does Not Exist | | | *Tire Depth of 5/32 or greater is considered normal | | | |

Vehicle Condition

Wear and Tear

| | | | |
|---|----------------------|------------|------------|
| 1 | Front Bumper Cover | Bug Damage | Acceptable |
| 2 | Left Front Fender | Chipped | 1 |
| 3 | Left Front Door | Chipped | 2 |
| 4 | Left Front Seat Back | Torn | 1" to 2" |

Condition Report

Completed by Alliance Inspection Management

2007 Porsche 911

VIN: WPOCA29937S765208

Vehicle Inspection Points

Legend: ● Item inspected and is ok ● Item inspected and contains an issue ○ Item is not present or could not be inspected

Exterior

| | | | |
|---|---|--|---|
| Vehicle Identification Number On Door Jam | ● | Vehicle Identification Number On Dashboard | ● |
| Front Lamps | ● | Rear Lamps | ● |
| Side Marker | ● | Frame / Unibody | ● |
| Roof Rack | ○ | Door And Side Moldings | ● |
| Wiper Blades/Arms | ● | Check Engine Compartment for Fluid Leaks | ● |
| Check Transmission For Leaks | ● | Battery | ● |
| Fluid Levels | ● | Belts/Hoses | ● |
| Emission Sticker | ● | | |

Interior

| | | | |
|--------------------------------|---|-----------------------------------|---|
| Power Door Locks | ● | Alarm | ● |
| Back up Camera | ● | Navigation/Entertainment System | ● |
| | | Notes: Inoperable / Broken | |
| Owners Manual | ● | CD/DVD | ● |
| Radio/Speakers | ● | Cooled/Heated Seats | ● |
| AC/Heater | ● | Trunk Release | ● |
| Tilt Steering Column Functions | ● | Parking Brake | ● |
| Dome Light | ○ | Knobs, Buttons and Other Controls | ● |
| Horn Functions | ● | Hood Release | ● |
| Hazard Lights | ● | Power Mirrors | ● |
| Power Seats | ● | Power Sunroof | ○ |
| Seatbelts | ● | Power Windows | ● |
| Carpet - Front | ● | Warning Lights | ● |
| Headliner Condition | ● | Convertible Top Operational | ● |
| Interior Trim | ● | Cargo Area Carpet | ● |
| First Aid Kit If Applicable | ○ | Spare Tire | ○ |
| Tailgate Closing Assist | ○ | Toolkit Complete | ○ |
| Carpet - Rear | ● | | |

Date : 18 Apr 2014

Signature : _____

V1.3B2B

Condition Report


Completed by Alliance Inspection Management

2007 Porsche 911

VIN: WPOCA29937S765208

Vehicle Pictures

Picture Description : **VIN**



Picture Description : **Wheel**




Picture Description : **Left Front Corner**



Picture Description : **Dashboard**



Picture Description : **Front Interior**



Picture Description : **Front Interior**



Condition Report

Completed by Alliance Inspection Management

2007 Porsche 911

VIN: WP0CA29937S765208

Picture Description : **Front Interior**



Picture Description : **Wheel**



Picture Description : **Front Interior**



Picture Description : **Odometer**



Picture Description : **Front Interior**



Picture Description : **Cargo Area**



Condition Report

Completed by Alliance Inspection Management

2007 Porsche 911

VIN: WP0CA29937S765208

Picture Description : **Right Rear Corner**



Picture Description : **Front Interior**



Picture Description : **Wheel**



Picture Description : **Front Interior**



Picture Description : **Wheel**



Picture Description : **Front Interior**



Condition Report

Completed by Alliance Inspection Management

2007 Porsche 911

VIN: WP0CA29937S765208

Picture Description : **Left Front Corner**



Picture Description : **Front Interior**



Picture Description : **Front Interior**



Condition Report

Completed by Alliance Inspection Management



2007 Porsche 911

VIN: WP0CA29937S765208

Damage Pictures

Picture Description : **No Picture**

