

# Condition Report

Completed by Alliance Inspection Management



## 2013 Porsche 911

VIN: WPOAB2A94DS122135



### Vehicle Information

Year : 2013  
Brand : Porsche  
Model : 911  
Series : S  
Body Type : Coupe  
Drive Type : RWD  
Engine : 3.8L, 6, Gas  
Transmission : 6-Speed A/T  
Mileage : 5735  
Exterior Color : Silver  
Trim Color : Black  
Trim Type : Leather

### Inspection Details

Inspection Date : 23 Apr 2014 11:40 AM  
Inspection ID : 450934  
Inspector : 4491  
Grade : A

Inspection Notes : 6 Point Undercarriage Inspection Completed. Engine Cradle OK.  
Direct Injected.  
No spare on this model.

### Vehicle Accessories

- A/C
- Air Conditioner
- Automatic On/Off Headlights
- Bucket Seats
- Climate Controlled Seats With Cooling Fun
- Driver Air Bag
- Heated And Cooled Front Seats
- Leather Seats
- Mirror Memory
- Passenger Air Bag On/Off Switch
- Power Moonroof / Sunroof
- Power Windows
- Rear Sonar System
- Side Airbags
- Sport Tuned Suspension
- Tires - Rear Performance
- Ventilated Leather Trimmed Net Seats
- ABS
- Alloy Wheels
- Auxiliary Audio Input
- CD Player
- Cruise Control
- Engine Immobilizer
- Heated Mirrors
- Leather Seats (3rd Row Is Vinyl)
- Navigation System
- Power Bucket Seats
- Power Passenger Seat
- Premium Sound System
- Rear Spoiler
- Sirius Satellite Radio
- Sun/Moon Roof
- Traction Control
- Wood Trim Finishes
- AM/FM Stereo
- Aluminum Wheels
- Bluetooth
- Child Safety Locks
- Curtain/Side Airbags
- Floor Mats
- Intelligent Key
- Leather Steering Wheel
- Pass-Through Rear Seat
- Power Door Locks
- Power Seat W/Memory
- Rear Bench Seat
- Rearview Monitor
- Sport Brakes
- Tire Pressure Monitor
- Trip Computer
- Xenon Headlamps
- Adjustable Steering Wheel
- Anti Lock Braking System
- Brake Assist
- Climate Control
- Daytime Running Lights
- Front Reading Lamps
- Intermittent Wipers
- MP3 Player
- Passenger Air Bag
- Power Driver Seat
- Power Steering
- Rear Head Air Bag
- Satellite Radio
- Sport Package
- Tires - Front Performance
- Vehicle Dynamic Control
- Xm Satellite Radio

### Tire Information

	Manufacturer	Size	Depth		Manufacturer	Size	Depth
Left Front :	Pirelli	245/35-20	8/32	Right Front :	Pirelli	245/35-20	8/32
Left Rear :	Pirelli	295/30-20	9/32	Right Rear :	Pirelli	295/30-20	9/32
Spare :	Pirelli	245/35-20	8/32	*Tire Depth of 5/32 or greater is considered normal			

### Vehicle Condition

#### Wear and Tear

1

# Condition Report

Completed by Alliance Inspection Management



2013 Porsche 911

VIN: WPOAB2A94DS122135

## Vehicle Inspection Points

**Legend:** ● Item inspected and is ok    ● Item inspected and contains an issue    ○ Item is not present or could not be inspected

### Exterior

Vehicle Identification Number On Door Jam	●	Vehicle Identification Number On Dashboard	●
Front Lamps	●	Rear Lamps	●
Side Marker	●	Frame / Unibody	●
Roof Rack	●	Door And Side Moldings	●
Wiper Blades/Arms	●	Check Engine Compartment for Fluid Leaks	●
Check Transmission For Leaks	●	Battery	●
Fluid Levels	●	Belts/Hoses	●
Emission Sticker	●		

### Interior

Power Door Locks	●	Alarm	●
Back up Camera	●	Navigation/Entertainment System	●
Owners Manual	●	CD/DVD	●
Radio/Speakers	●	Cooled/Heated Seats	●
AC/Heater	●	Trunk Release	●
Tilt Steering Column Functions	●	Parking Brake	●
Dome Light	●	Knobs, Buttons and Other Controls	●
Horn Functions	●	Hood Release	●
Hazard Lights	●	Power Mirrors	●
Power Seats	●	Power Sunroof	●
Seatbelts	●	Power Windows	●
Carpet - Front	●	Warning Lights	●
Headliner Condition	●	Convertible Top Operational	○
Interior Trim	●	Cargo Area Carpet	●
First Aid Kit If Applicable	○	Spare Tire	○
Tailgate Closing Assist	○	Toolkit Complete	●
Carpet - Rear	●		

Date : 23 Apr 2014

Signature : \_\_\_\_\_

V1.3B2B

# Condition Report

Completed by Alliance Inspection Management

2013 Porsche 911

VIN: WPOAB2A94DS122135

## Vehicle Pictures

Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Cargo Area**



Picture Description : **Other**



Picture Description : **Wheel**





# Condition Report

Completed by Alliance Inspection Management


2013 Porsche 911

VIN: WPOAB2A94DS122135


Picture Description : **Odometer**



Picture Description : **VIN**



Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Other**





# Condition Report

Completed by Alliance Inspection Management

2013 Porsche 911

VIN: WP0AB2A94DS122135

Picture Description : **Other**



Picture Description : **Right Rear Corner**



Picture Description : **Wheel**



Picture Description : **Dashboard**



Picture Description : **Other**



Picture Description : **Other**





# Condition Report

Completed by Alliance Inspection Management

2013 Porsche 911

VIN: WP0AB2A94DS122135

Picture Description : **Wheel**



Picture Description : **Other**



Picture Description : **Front Interior**



Picture Description : **Left Front Corner**



Picture Description : **Wheel**



## Condition Report

Completed by Alliance Inspection Management



**2013 Porsche 911**

VIN: WPOAB2A94DS122135

### Damage Pictures

Picture Description : **No Picture**

