Condition Report

Completed by Alliance Inspection Management

2008 Lexus LS 460

VIN: JTHBL46F885062066

Vehicle Information

Year :	2008
Brand :	Lexus
Model :	LS 460
Series :	
Body Type :	Sedan
Drive Type :	RWD
Engine :	4.6L, 8, Gas
Transmission :	8-Speed A/T
Mileage :	56218
Exterior Color :	Silver
Trim Color :	Black
Trim Type :	Leather

Inspection Details

Inspection Date :	23 Apr 2014 12:17 PM
Inspection ID :	450932
Inspector :	4491
Grade :	A

Inspection Notes :

Vehicle Accessories

- A/C
- Advanced Climate Control
- Anti Lock Braking System
- Brake Assist
- Child Safety Locks
- Curtain\Side Airbags
- Engine Immobilizer
- Heated Mirrors
- Leather Seats
- Media Card Reader
- Power Bucket Seats
- Power Moonroof / Sunroof
- Power Windows
- Rear Reading Lamps
- Side Airbags
- Tires - Front Performance
- Vehicle Dynamic Control
- Xenon Headlamps
- ABS
- Air Conditioner
- Automatic On/Off Headlights
- Bucket Seats
- Climate Control
- Daytime Running Lights
- Floor Mats
- Intelligent Key
- Leather Seats (3rd Row Is Vinyl)
- Mirror Memory
- Power Door Locks
- Power Passenger Seat
- Premium Sound System
- Rear Sonar System
- Sirius Satellite Radio
- Tires - Rear Performance
- Ventilated Leather Trimmed Net Seats
- Xm Satellite Radio
- AM/FM Stereo
- Alloy Wheels
- Auxiliary Audio Input
- CD Changer
- Climate Controlled Seats With Cooling Fun
- Driver Air Bag
- Front Reading Lamps
- Intermittent Wipers
- Leather Steering Wheel
- Navigation System
- Power Driver Seat
- Power Seat W/Memory
- Rear Head Air Bag
- Rearview Monitor
- Sun/Moon Roof
- Traction Control
- Wheel Locks
- Adjustable Steering Wheel
- Aluminum Wheels
- Bluetooth
- CD Player
- Cruise Control
- Dual Front Zone Automatic Temp Control
- Heated And Cooled Front Seats
- Keyless Start
- MP3 Player
- Passenger Air Bag
- Power Locks
- Power Steering
- Rear Parking Aid
- Satellite Radio
- Tire Pressure Monitor
- Trip Computer
- Wood Trim Finishes

Tire Information

	Manufacturer	Size	Depth
Left Front :	Bridgestone	235/50-18	9/32
Left Rear :	Bridgestone	235/50-18	9/32
Spare :	Bridgestone	235/50-18	11/32

	Manufacturer	Size	Depth
Right Front :	Bridgestone	235/50-18	9/32
Right Rear :	Bridgestone	235/50-18	9/32

*Tire Depth of 5/32 or greater is considered normal

Vehicle Condition

Wear and Tear

1	Hood	Prev Repair	Substd Repair
	Touch up used, should be refinished properly.		

Condition Report

Completed by Alliance Inspection Management

Alliance Inspection Management

2008 Lexus LS 460

VIN: JTHBL46F885062066

Vehicle Inspection Points

Legend: ● **Item inspected and is ok** ● **Item inspected and contains an issue** ❍ **Item is not present or could not be inspected**

Exterior

Vehicle Identification Number On Door Jam	●	Vehicle Identification Number On Dashboard	●
Front Lamps	●	Rear Lamps	●
Side Marker	●	Frame / Unibody	●
Roof Rack	●	Door And Side Moldings	●
Wiper Blades/Arms	●	Check Engine Compartment for Fluid Leaks	●
Check Transmission For Leaks	●	Battery	●
Fluid Levels	●	Belts/Hoses	●
Emission Sticker	●		

Interior

Power Door Locks	●	Alarm	●
Back up Camera	●	Navigation/Entertainment System	●
Owners Manual	●	CD/DVD	●
Radio/Speakers	●	Cooled/Heated Seats	●
AC/Heater	●	Trunk Release	●
Tilt Steering Column Functions	●	Parking Brake	●
Dome Light	●	Knobs, Buttons and Other Controls	●
Horn Functions	●	Hood Release	●
Hazard Lights	●	Power Mirrors	●
Power Seats	●	Power Sunroof	●
Seatbelts	●	Power Windows	●
Carpet - Front	●	Warning Lights	●
Headliner Condition	●	Convertible Top Operational	❍
Interior Trim	●	Cargo Area Carpet	●
First Aid Kit If Applicable	●	Spare Tire	●
Tailgate Closing Assist	❍	Toolkit Complete	●
Carpet - Rear	●		

Date : 23 Apr 2014

Signature : _____

V1.3B2B

Condition Report

Completed by Alliance Inspection Management

2008 Lexus LS 460

VIN: JTHBL46F885062066

Vehicle Pictures

Picture Description : **Other**

Picture Description : **Wheel**

Picture Description : **Other**



Picture Description : **Other**

Picture Description : **Other**

Picture Description : **VIN**



Condition Report

Completed by Alliance Inspection Management

Alliance Inspection Management

2008 Lexus LS 460

VIN: JTHBL46F885062066

Picture Description : **Right Rear Corner**

Picture Description : **Cargo Area**

Picture Description : **Other**

Picture Description : **Wheel**

Picture Description : **Other**

Picture Description : **Other**

Condition Report

Completed by Alliance Inspection Management

2008 Lexus LS 460

VIN: JTHBL46F885062066

Picture Description : **Other**

Picture Description : **Other**

Picture Description : **Other**

Picture Description : **Wheel**

Picture Description : **Other**

Picture Description : **Other**

Condition Report

Completed by Alliance Inspection Management

2008 Lexus LS 460

VIN: JTHBL46F885062066

Picture Description : **Odometer**

Picture Description : **Wheel**

Picture Description : **Wheel**

Picture Description : **Dashboard**

Picture Description : **Front Interior**

Picture Description : **Other**

Condition Report

Completed by Alliance Inspection Management

2008 Lexus LS 460

VIN: JTHBL46F885062066

Picture Description : **Left Front Corner**

Condition Report

Completed by Alliance Inspection Management

2008 Lexus LS 460

VIN: JTHBL46F885062066

Damage Pictures

Picture Description : **Hood Prev Repair Substd Repair**