

Condition Report

Completed by Alliance Inspection Management

2007 Porsche 911

VIN: WP0CA29967S765302



Vehicle Information

Year : 2007
Brand : Porsche
Model : 911
Series : Carrera 4
Body Type : Convertible
Drive Type : AWD
Engine : 3.6L, 6, Gas
Transmission : 6-Speed M/T
Mileage : 27322
Exterior Color : Silver
Trim Color : Blue
Trim Type : Leather

Inspection Details

Inspection Date : 30 Apr 2014 4:28 PM
Inspection ID : 455371
Inspector : 4882
Grade : A

Inspection Notes : NO SPARE

NO UNUSAL VIBRATIONS WERE ENCOUNTERED DURING IDLE THROUGHOUT INSPECTION. ALL ELECTRICAL WERE TESTED AND IN WORKING CONDITION DURING INSPECTION PROCESS. CONVERTIBLE TOP WORKING CONDITION(NO DAMAGE) . NO STRUCTURAL DAMAGE FOUND. MINIMAL BODY DAMAGES FOUND (NOTED ON REPORT). VEHICLE IN EXCELLENT CONDITION. INTERIOR IS EXCELLENT

Vehicle Accessories

- A/C
- Aluminum Wheels
- Climate Control
- Heated Mirrors
- MP3 Player
- Power Door Locks
- Power Windows
- Tire Pressure Monitor
- Trip Computer
- ABS
- Bucket Seats
- Cruise Control
- Intermittent Wipers
- Navigation System
- Power Driver Seat
- Premium Sound System
- Tires - Front Performance
- AM/FM Stereo
- CD Changer
- Driver Air Bag
- Leather Seats
- Pass-Through Rear Seat
- Power Passenger Seat
- Rear Bench Seat
- Tires - Rear Performance
- Adjustable Steering Wheel
- CD Player
- Floor Mats
- Leather Steering Wheel
- Passenger Air Bag
- Power Steering
- Rear Spoiler
- Traction Control

Tire Information

	Manufacturer	Size	Depth		Manufacturer	Size	Depth
Left Front :	Michelin	235/35-19	6/32	Right Front :	Michelin	235/35-19	6/32
Left Rear :	Michelin	305/30-19	5/32	Right Rear :	Michelin	305/30-19	5/32
Spare :	Other	Other	5/32	*Tire Depth of 5/32 or greater is considered normal			

Vehicle Condition

Wear and Tear

1	Front Bumper Cover NOT IN CLEAR SIGHTLINE	Curb Rash	9" to 10"
2	Right Front Wheel	Curb Rash	6" to 7"
3	Right Rear Wheel	Curb Rash	11" to 12"
4	Left Front Door	Chipped	6

Condition Report

Completed by Alliance Inspection Management

2007 Porsche 911

VIN: WPOCA29967S765302

MINOR DOOR EDGE CHIPS

Vehicle Inspection Points

Legend: ● Item inspected and is ok ● Item inspected and contains an issue ○ Item is not present or could not be inspected

Exterior

Vehicle Identification Number On Door Jam	●	Vehicle Identification Number On Dashboard	●
Front Lamps	●	Rear Lamps	●
Side Marker	●	Frame / Unibody	●
Roof Rack	○	Door And Side Moldings	●
Wiper Blades/Arms	●	Check Engine Compartment for Fluid Leaks	●
Check Transmission For Leaks	●	Battery	●
Fluid Levels	●	Belts/Hoses	●
Emission Sticker	●		

Interior

Power Door Locks	●	Alarm	●
Back up Camera	●	Navigation/Entertainment System	●
Owners Manual	●	CD/DVD	●
Radio/Speakers	●	Cooled/Heated Seats	●
AC/Heater	●	Trunk Release	●
Tilt Steering Column Functions	●	Parking Brake	●
Dome Light	●	Knobs, Buttons and Other Controls	●
Horn Functions	●	Hood Release	●
Hazard Lights	●	Power Mirrors	●
Power Seats	●	Power Sunroof	○
Seatbelts	●	Power Windows	●
Carpet - Front	●	Warning Lights	●
Headliner Condition	●	Convertible Top Operational	●
Interior Trim	●	Cargo Area Carpet	●
First Aid Kit If Applicable	●	Spare Tire	●
Tailgate Closing Assist	●	Toolkit Complete	●
Carpet - Rear	●		

Date : 30 Apr 2014

Signature : _____

V1.3B2B

Condition Report


Completed by Alliance Inspection Management

2007 Porsche 911

VIN: WP0CA29967S765302

Vehicle Pictures

Picture Description : **Other**



Picture Description : **Wheel**



Picture Description : **Cargo Area**



Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Front Interior**



Condition Report

Completed by Alliance Inspection Management

2007 Porsche 911

VIN: WPOCA29967S765302


Picture Description : **Other**



Picture Description : **Dashboard**



Picture Description : **VIN**



Picture Description : **Wheel**



Picture Description : **Other**



Picture Description : **Other**




Condition Report

Completed by Alliance Inspection Management

2007 Porsche 911

VIN: WPOCA29967S765302

Picture Description : **Other**



Picture Description : **Cargo Area**



Picture Description : **Dashboard**




Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Other**



Condition Report

Completed by Alliance Inspection Management

2007 Porsche 911

VIN: WP0CA29967S765302

Picture Description : **Dashboard**



Picture Description : **Odometer**



Picture Description : **Other**



Picture Description : **Front Interior**



Picture Description : **Other**



Picture Description : **Other**



Condition Report

Completed by Alliance Inspection Management

2007 Porsche 911

VIN: WPOCA29967S765302

Picture Description : **VIN**



Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Wheel**



Picture Description : **Other**



Picture Description : **Other**



Condition Report

Completed by Alliance Inspection Management

2007 Porsche 911

VIN: WP0CA29967S765302

Picture Description : **Left Front Corner**



Picture Description : **Other**



Picture Description : **Right Rear Corner**



Picture Description : **Wheel**



Picture Description : **Cargo Area**



Picture Description : **Other**



Condition Report

Completed by Alliance Inspection Management

2007 Porsche 911

VIN: WPOCA29967S765302

Damage Pictures

Picture Description : **Wheel Curb Rash 6" to 7"**




Picture Description : **Wheel Curb Rash 6" to 7"**



Picture Description : **Wheel Curb Rash 6" to 7"**



Picture Description : **Bumper Cover Curb Rash 9" to 10"**



Picture Description : **Bumper Cover Curb Rash 9" to 10"**



Picture Description : **Wheel Curb Rash 11" to 12"**



Condition Report

Completed by Alliance Inspection Management

2007 Porsche 911

VIN: WP0CA29967S765302

Picture Description : **Door Chipped 6**



Picture Description : **Wheel Curb Rash 11" to 12"**



Picture Description : **Wheel Curb Rash 11" to 12"**



Picture Description : **Wheel Curb Rash 11" to 12"**



Picture Description : **Wheel Curb Rash 11" to 12"**

Picture Description : **Door Chipped 6**

