

Condition Report

Completed by Alliance Inspection Management

2013 Land Rover Range Rover Sport

VIN: SALGS2EF4DA105845



Vehicle Information

Year : 2013
Brand : Land Rover
Model : Range Rover Sport
Series : HSE
Body Type : SUV
Drive Type : 4WD
Engine : 5.0L, 8, Gas
Transmission : 8-Speed A/T
Mileage : 10068
Exterior Color : Black
Trim Color : Black
Trim Type : Leather

Inspection Details

Inspection Date : 30 Apr 2014 2:19 PM
Inspection ID : 455369
Inspector : 4882
Grade : A

Inspection Notes : NO UNUSUAL NOISES OR VIBRATIONS WERE ENCOUNTERED DURING IDLE THROUGHOUT INSPECTION.. ALL ELECTRICAL WERE TESTED AND IN WORKING CONDITION DURING INSPECTION PROCESS. NO STRUCTURAL DAMAGE FOUND. OEM GRILLE HAS BEEN CUSTOMIZED TO MATCH PAINTED SURFACES AS WELL AS REMOVAL OF EMBLEMS FOR "BLACK OUT" EFFECT. REFINISH WORK IS VERY NICEY DONE. EXCELLENT CONDITION INSIDE AND OUT.

Vehicle Accessories

- A/C
- Air Suspension
- Brake Assist
- Climate Control
- Floor Mats
- Keyless Start
- Navigation System
- Power Door Locks
- Power Windows
- Rear Bench Seat
- Sun/Moon Roof
- Tires - Rear Performance
- ABS
- Aluminum Wheels
- Bucket Seats
- Cruise Control
- Heated Mirrors
- Leather Seats
- Panoramic Roof
- Power Driver Seat
- Premium Sound System
- Rear Head Air Bag
- Supercharged
- Traction Control
- AM/FM Stereo
- Auxiliary Audio Input
- CD Player
- Driver Air Bag
- Heated Rear Seat(s)
- Leather Steering Wheel
- Pass-Through Rear Seat
- Power Passenger Seat
- Privacy Glass
- Rear Parking Aid
- Tire Pressure Monitor
- Adjustable Steering Wheel
- Blind Spot Monitor
- Child Safety Locks
- Entertainment System
- Intermittent Wipers
- MP3 Player
- Passenger Air Bag
- Power Steering
- Rear A/C
- Satellite Radio
- Tires - Front Performance

Tire Information

	Manufacturer	Size	Depth		Manufacturer	Size	Depth
Left Front :	Goodyear	275/45-21	7/32	Right Front :	Goodyear	275/45-21	7/32
Left Rear :	Goodyear	275/45-21	7/32	Right Rear :	Goodyear	275/45-21	7/32
Spare :	Goodyear	275/45-21	8/32	*Tire Depth of 5/32 or greater is considered normal			

Vehicle Condition

Wear and Tear

1

Condition Report

Completed by Alliance Inspection Management

2013 Land Rover Range Rover Sport

VIN: SALGS2EF4DA105845

Vehicle Inspection Points

Legend: ● Item inspected and is ok ● Item inspected and contains an issue ○ Item is not present or could not be inspected

Exterior

Vehicle Identification Number On Door Jam	●	Vehicle Identification Number On Dashboard	●
Front Lamps	●	Rear Lamps	●
Side Marker	●	Frame / Unibody	●
Roof Rack	○	Door And Side Moldings	●
Wiper Blades/Arms	●	Check Engine Compartment for Fluid Leaks	●
Check Transmission For Leaks	●	Battery	●
Fluid Levels	●	Belts/Hoses	●
Emission Sticker	●		

Interior

Power Door Locks	●	Alarm	●
Back up Camera	●	Navigation/Entertainment System	●
Owners Manual	●	CD/DVD	●
Radio/Speakers	●	Cooled/Heated Seats	●
AC/Heater	●	Trunk Release	●
Tilt Steering Column Functions	●	Parking Brake	●
Dome Light	●	Knobs, Buttons and Other Controls	●
Horn Functions	●	Hood Release	●
Hazard Lights	●	Power Mirrors	●
Power Seats	●	Power Sunroof	●
Seatbelts	●	Power Windows	●
Carpet - Front	●	Warning Lights	●
Headliner Condition	●	Convertible Top Operational	○
Interior Trim	●	Cargo Area Carpet	●
First Aid Kit If Applicable	●	Spare Tire	●
Tailgate Closing Assist	●	Toolkit Complete	●
Carpet - Rear	●		

Date : 30 Apr 2014

Signature : _____

V1.3B2B

Condition Report

Completed by Alliance Inspection Management

2013 Land Rover Range Rover Sport

VIN: SALGS2EF4DA105845

Vehicle Pictures

Picture Description : **Other**



Picture Description : **Wheel**



Picture Description : **Dashboard**



Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Cargo Area**



Condition Report

Completed by Alliance Inspection Management

2013 Land Rover Range Rover Sport

VIN: SALGS2EF4DA105845

Picture Description : **Dashboard**



Picture Description : **Other**



Picture Description : **Wheel**




Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Other**



Condition Report

Completed by Alliance Inspection Management

2013 Land Rover Range Rover Sport

VIN: SALGS2EF4DA105845

Picture Description : **Other**




Picture Description : **Dashboard**



Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Front Interior**



Condition Report

Completed by Alliance Inspection Management

2013 Land Rover Range Rover Sport

VIN: SALGS2EF4DA105845

Picture Description : **Other**



Picture Description : **Wheel**



Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Dashboard**



Condition Report

Completed by Alliance Inspection Management

2013 Land Rover Range Rover Sport

VIN: SALGS2EF4DA105845

Picture Description : **Dashboard**



Picture Description : **Odometer**



Picture Description : **Other**



Picture Description : **Other**



Picture Description : **VIN**



Picture Description : **Right Rear Corner**



Condition Report

Completed by Alliance Inspection Management

2013 Land Rover Range Rover Sport

VIN: SALGS2EF4DA105845

Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Wheel**



Picture Description : **Other**



Picture Description : **Left Front Corner**



Picture Description : **Dashboard**




Condition Report

Completed by Alliance Inspection Management

2013 Land Rover Range Rover Sport

VIN: SALGS2EF4DA105845

Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Other**



Condition Report

Completed by Alliance Inspection Management

2013 Land Rover Range Rover Sport

VIN: SALGS2EF4DA105845

Picture Description : **Front Interior**



Picture Description : **Wheel**



Condition Report

Completed by Alliance Inspection Management



2013 Land Rover Range Rover Sport

VIN: SALGS2EF4DA105845

Damage Pictures

Picture Description :

No Picture

