

Condition Report

Completed by Alliance Inspection Management

1995 Porsche 911 Carrera

VIN: WP0CA2996SS343426



Vehicle Information

Year : 1995
Brand : Porsche
Model : 911 Carrera
Series :
Body Type : Convertible
Drive Type : AWD
Engine : 3.6L, 6, Gas
Transmission : 6-Speed M/T
Mileage : 37440
Exterior Color : White
Trim Color : Grey
Trim Type : Leather

Inspection Details

Inspection Date : 06 Jun 2014 10:44 AM
Inspection ID : 480997
Inspector : 3661

Grade : A

Inspection Notes :

Vehicle Accessories

- A/C
- Bucket Seats
- Driver Air Bag
- Passenger Air Bag
- Power Steering
- Tires - Rear Performance
- ABS
- CD Player
- Heated Mirrors
- Power Door Locks
- Power Windows
- Wheel Locks
- AM/FM Stereo
- Climate Control
- Leather Seats
- Power Driver Seat
- Rear Spoiler
- Aluminum Wheels
- Cruise Control
- Leather Steering Wheel
- Power Passenger Seat
- Tires - Front Performance

Tire Information

	Manufacturer	Size	Depth		Manufacturer	Size	Depth
Left Front :	Michelin	205/50-17	8/32	Right Front :	Michelin	205/50-17	7/32
Left Rear :	Michelin	255/40-17	6/32	Right Rear :	Michelin	255/40-17	6/32
Spare :	Vredestein	165/70-16	4/32	*Tire Depth of 5/32 or greater is considered normal			

Vehicle Condition

Wear and Tear

1	Front Bumper Cover	Loose	Repair Required
2	Front Bumper Cover	Bug Damage	Acceptable
3	Left Front Door	Dent/No Paint Dmg	1" to 2"
4	CD Player	Inop	Repair Required

Vehicle Inspection Points

Condition Report

Completed by Alliance Inspection Management

1995 Porsche 911 Carrera

VIN: WPOCA2996SS343426

Legend: ● Item inspected and is ok ● Item inspected and contains an issue ○ Item is not present or could not be inspected

Exterior

Vehicle Identification Number On Door Jam	●	Vehicle Identification Number On Dashboard	●
Front Lamps	●	Rear Lamps	●
Side Marker	●	Frame / Unibody	●
Roof Rack	○	Door And Side Moldings	●
Wiper Blades/Arms	●	Check Engine Compartment for Fluid Leaks	●
Check Transmission For Leaks	●	Battery	●
Fluid Levels	●	Belts/Hoses	●
Emission Sticker	●		

Interior

Power Door Locks	●	Alarm	●
Back up Camera	○	Navigation/Entertainment System	○
Owners Manual	●	CD/DVD	●
		Notes: Inoperable / Broken	
Radio/Speakers	●	Cooled/Heated Seats	○
AC/Heater	●	Trunk Release	●
Tilt Steering Column Functions	●	Parking Brake	●
Dome Light	●	Knobs, Buttons and Other Controls	●
Horn Functions	●	Hood Release	●
Hazard Lights	●	Power Mirrors	●
Power Seats	●	Power Sunroof	○
Seatbelts	●	Power Windows	●
Carpet - Front	●	Warning Lights	●
Headliner Condition	●	Convertible Top Operational	●
Interior Trim	●	Cargo Area Carpet	●
First Aid Kit If Applicable	○	Spare Tire	●
Tailgate Closing Assist	○	Toolkit Complete	●
Carpet - Rear	●		

Date : 06 Jun 2014

Signature : _____

V1.3B2B

Condition Report

Completed by Alliance Inspection Management

1995 Porsche 911 Carrera


VIN: WPOCA2996SS343426

Vehicle Pictures

Picture Description : **Left Front Corner**



Picture Description : **VIN**



Picture Description : **Wheel**



Picture Description : **Front Interior**



Picture Description : **Front Interior**



Picture Description : **Dashboard**



Condition Report

Completed by Alliance Inspection Management

1995 Porsche 911 Carrera

VIN: WP0CA2996SS343426

Picture Description : **Wheel**



Picture Description : **Front Interior**



Picture Description : **Odometer**



Picture Description : **Right Rear Corner**



Picture Description : **Front Interior**



Picture Description : **Wheel**



Condition Report

Completed by Alliance Inspection Management

1995 Porsche 911 Carrera

VIN: WP0CA2996SS343426

Picture Description : **Front Interior**



Picture Description : **Wheel**



Picture Description : **Front Interior**



Picture Description : **Front Interior**



Picture Description : **Cargo Area**



Picture Description : **Front Interior**



Condition Report

Completed by Alliance Inspection Management

1995 Porsche 911 Carrera

VIN: WP0CA2996SS343426

Picture Description : **Front Interior**



Picture Description : **Front Interior**



Condition Report

Completed by Alliance Inspection Management

1995 Porsche 911 Carrera

VIN: WPOCA2996SS343426

Damage Pictures

Picture Description : **Bumper Cover Loose Repair Required**



Picture Description : **CD Player Inop Repair Required**

