

# Condition Report

Completed by Alliance Inspection Management



## 2008 Porsche Cayenne

VIN: WP1AA29PX8LA1867



### Vehicle Information

Year : 2008  
 Brand : Porsche  
 Model : Cayenne  
 Series : Man  
 Body Type : SUV  
 Drive Type : AWD  
 Engine : 3.6L, 6, Gas  
 Transmission : 6-Speed M/T  
 Mileage : 70056  
 Exterior Color : Black  
 Trim Color : Black  
 Trim Type : Leather

### Inspection Details

Inspection Date : 18 Jul 2014 10:04 AM  
 Inspection ID : 502571  
 Inspector : 4875  
 Grade : A

Inspection Notes : Tire\_Loc=Spare MFR=Vredestein

### Vehicle Accessories

- A/C
- Advanced Climate Control
- Anti Lock Braking System
- CD Player
- Climate Control
- Dual Front Zone Automatic Temp Control
- Front Reading Lamps
- Leather Seats
- Pass-Through Rear Seat
- Power Driver Bucket Seat
- Power Locks
- Power Steering
- Rear A/C
- Satellite Radio
- Tires - Front Performance
- Trip Computer
- ABS
- Air Conditioner
- Automatic On/Off Headlights
- Cargo Shade
- Cruise Control
- Dual Zone Automatic Temp Control
- Front Side Airbags
- Leather Steering Wheel
- Passenger Air Bag
- Power Driver Seat
- Power Moonroof / Sunroof
- Power Windows
- Rear Bench Seat
- Side Airbags
- Tires - Rear Performance
- Xenon Headlamps
- AM/FM Stereo
- Alloy Wheels
- Bluetooth
- Cargo/Tonneau Cover
- Curtain/Side Airbags
- Engine Immobilizer
- Heated Mirrors
- Mirror Memory
- Power Bucket Seats
- Power Front Seat
- Power Passenger Seat
- Premium Sound System
- Rear Head Air Bag
- Sirius Satellite Radio
- Tow Ball/Hitch
- Adjustable Steering Wheel
- Aluminum Wheels
- Bucket Seats
- Child Safety Locks
- Driver Air Bag
- Floor Mats
- Intermittent Wipers
- Navigation System
- Power Door Locks
- Power Hatch
- Power Seat W/Memory
- Privacy Glass
- Rear Reading Lamps
- Sun/Moon Roof
- Traction Control

### Tire Information

	Manufacturer	Size	Depth		Manufacturer	Size	Depth
Left Front :	Bridgestone	255/55-18	9/32	Right Front :	Bridgestone	255/55-18	9/32
Left Rear :	Bridgestone	255/55-18	10/32	Right Rear :	Bridgestone	255/55-18	10/32
Spare :	Other	195/75-18	5/32	*Tire Depth of 5/32 or greater is considered normal			

### Vehicle Condition

#### Wear and Tear

<b>1</b>	Hood	Mult Scratches/Light	4
<b>2</b>	Front Bumper Cover	Multiple Chips	5
<b>3</b>	Left Front Fender	Mult Scratches/Light	10 or More

## Condition Report

Completed by Alliance Inspection Management



### 2008 Porsche Cayenne

VIN: WP1AA29PX8LA1867

4	Left Front Mirror Cover	Scuffed	1/8" to 1/2"
5	Left Front Door	Mult Scratches/Light	4
6	Left Rear Door	Scratch Light	1/2" to 1"
7	Rear Bumper Cover	Chipped	1
8	Rear Bumper Cover	Scuffed	3" to 4"
9	Deck Lid	Mult Scratches/Light	3
10	Right Qtr Panel	Scratch Light	1" to 2"
11	Right Rear Door	Scuffed	1" to 2"
12	Right Front Door	Scuffed	1/8" to 1/2"
13	Right Front Fender	Dent/No Paint Dmg	PDR/1
14	Right Front Fender	Prev Repair	Acceptable
15	Roof	Mult Scratches/Light	5
16	Roof	Scuffed	2" to 3"
17	Left Qtr Panel	Mult Scratches/Light	3

### Vehicle Inspection Points

# Condition Report

Completed by Alliance Inspection Management



## 2008 Porsche Cayenne

VIN: WP1AA29PX8LA1867

**Legend:** ● Item inspected and is ok    ● Item inspected and contains an issue    ○ Item is not present or could not be inspected

### Exterior

Vehicle Identification Number On Door Jam	●	Vehicle Identification Number On Dashboard	●
Front Lamps	●	Rear Lamps	●
Side Marker	●	Frame / Unibody	●
Roof Rack	○	Door And Side Moldings	●
Wiper Blades/Arms	●	Check Engine Compartment for Fluid Leaks	●
Check Transmission For Leaks	●	Battery	●
Fluid Levels	●	Belts/Hoses	●
Emission Sticker	●		

### Interior

Power Door Locks	●	Alarm	●
Back up Camera	○	Navigation/Entertainment System	●
Owners Manual	●	CD/DVD	●
Radio/Speakers	●	Cooled/Heated Seats	○
AC/Heater	●	Trunk Release	●
Tilt Steering Column Functions	●	Parking Brake	●
Dome Light	●	Knobs, Buttons and Other Controls	●
Horn Functions	●	Hood Release	●
Hazard Lights	●	Power Mirrors	●
Power Seats	●	Power Sunroof	●
Seatbelts	●	Power Windows	●
Carpet - Front	●	Warning Lights	●
Headliner Condition	●	Convertible Top Operational	○
Interior Trim	●	Cargo Area Carpet	●
First Aid Kit If Applicable	●	Spare Tire	●
Tailgate Closing Assist	●	Toolkit Complete	●
Carpet - Rear	●		

Date : 18 Jul 2014

Signature : \_\_\_\_\_

V1.3B2B

# Condition Report

Completed by Alliance Inspection Management

## 2008 Porsche Cayenne

VIN: WP1AA29PX8LA1867

### Vehicle Pictures

Picture Description : **Other**



Picture Description : **Wheel**



Picture Description : **Other**



Picture Description : **Right Rear Corner**



Picture Description : **Wheel**



Picture Description : **Left Front Corner**



# Condition Report

Completed by Alliance Inspection Management

## 2008 Porsche Cayenne

VIN: WP1AA29PX8LA1867

Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Dashboard**



Picture Description : **Wheel**



Picture Description : **Front Interior**



# Condition Report

Completed by Alliance Inspection Management

## 2008 Porsche Cayenne

VIN: WP1AA29PX8LA1867

Picture Description : **Other**




Picture Description : **Odometer**



Picture Description : **Wheel**



Picture Description : **Other**



Picture Description : **Cargo Area**



Picture Description : **Other**




# Condition Report

Completed by Alliance Inspection Management

## 2008 Porsche Cayenne

VIN: WP1AA29PX8LA1867

Picture Description : **VIN**



Picture Description : **Other**



Picture Description : **Other**



# Condition Report

Completed by Alliance Inspection Management



**2008 Porsche Cayenne**

VIN: WP1AA29PX8LA1867

## Damage Pictures

Picture Description : **No Picture**

