

# Condition Report

Completed by Alliance Inspection Management



## 2008 GMC Yukon XL Denali

VIN: 1GKFK668081103403



### Vehicle Information

Year : 2008  
 Brand : GMC  
 Model : Yukon XL Denali  
 Series :  
 Body Type : SUV  
 Drive Type : AWD  
 Engine : 6.2L, 8, Gas  
 Transmission : 6-Speed A/T  
 Mileage : 61913  
 Exterior Color : Black  
 Trim Color : Black  
 Trim Type : Leather

### Inspection Details

Inspection Date : 18 Jul 2014 10:22 AM  
 Inspection ID : 502558  
 Inspector : 4875  
 Grade : B

Inspection Notes :

### Vehicle Accessories

- A/C
- Advanced Climate Control
- Automatic On/Off Headlights
- Bucket Seats
- Chrome Wheels
- Driver Air Bag
- Electrochromic Rearview Mirror
- Front Reading Lamps
- Heated Rear Seat(s)
- Leather Seats
- Navigation System
- Power Door Locks
- Power Hatch
- Power Passenger Seat
- Premium Sound System
- Rear Parking Aid
- Roof Rails
- Tire Pressure Monitor
- Tow Hooks
- Xm Satellite Radio
- ABS
- Air Conditioner
- Auxiliary Audio Input
- CD Changer
- Climate Control
- Dual Front Zone Automatic Temp Control
- Engine Immobilizer
- Front Side Airbags
- Heated Rear Seats
- Leather Steering Wheel
- Pass-Through Rear Seat
- Power Driver Bucket Seat
- Power Liftgate
- Power Seat W/Memory
- Privacy Glass
- Rear Reading Lamps
- Satellite Radio
- Tires - Front Performance
- Traction Control
- AM/FM Stereo
- Air Suspension
- Bluetooth
- CD Player
- Cruise Control
- Dual Zone Automatic Temp Control
- Entertainment System
- Heated Front Seats
- Integrated Turn Signal Mirrors
- Luggage Rack
- Passenger Air Bag
- Power Driver Seat
- Power Locks
- Power Steering
- Rear A/C
- Rear Seat Audio Controls
- Side Airbags
- Tires - Rear Performance
- Wood Trim Finishes
- Adjustable Steering Wheel
- Anti Lock Braking System
- Bose Audio
- Child Safety Locks
- Curtain\Side Airbags
- Dvd - Single Screen
- Floor Mats
- Heated Mirrors
- Intermittent Wipers
- MP3 Player
- Power Bucket Seats
- Power Front Seat
- Power Moonroof / Sunroof
- Power Windows
- Rear Head Air Bag
- Rearview Monitor
- Sun/Moon Roof
- Tow Ball/Hitch
- Xenon Headlamps

### Tire Information

	Manufacturer	Size	Depth		Manufacturer	Size	Depth
Left Front :	Goodyear	275/55-20	9/32	Right Front :	Goodyear	275/55-20	9/32
Left Rear :	Goodyear	275/55-20	10/32	Right Rear :	Goodyear	275/55-20	10/32
Spare :	Goodyear	265/70-17	11/32	*Tire Depth of 5/32 or greater is considered normal			

### Vehicle Condition

Wear and Tear

## Condition Report

Completed by Alliance Inspection Management



### 2008 GMC Yukon XL Denali

VIN: 1GKFK668081103403

1	Hood	Chipped	3
2	Front Bumper Cover	Chipped	4
3	Front Bumper Cover	Mult Scratches/Heavy	6
4	Rear Bumper Molding	Scratch Heavy	1/2" to 1"
5	Deck Lid	Scuffed	1" to 2"
6	Right Qtr Panel	Chipped	1
7	Right Rear Door	Scuffed	1" to 2"
8	Right Front Door	Scratch Heavy	1" to 2"
9	Right Front Door	Scuffed	1/2" to 1"
10	Right Front Bumper Cover	Scuffed	5" to 6"

### Vehicle Inspection Points

# Condition Report

Completed by Alliance Inspection Management



## 2008 GMC Yukon XL Denali

VIN: 1GKFK668081103403

**Legend:** ● Item inspected and is ok    ● Item inspected and contains an issue    ○ Item is not present or could not be inspected

### Exterior

Vehicle Identification Number On Door Jam	●	Vehicle Identification Number On Dashboard	●
Front Lamps	●	Rear Lamps	●
Side Marker	●	Frame / Unibody	●
Roof Rack	●	Door And Side Moldings	●
Wiper Blades/Arms	●	Check Engine Compartment for Fluid Leaks	●
Check Transmission For Leaks	●	Battery	●
Fluid Levels	●	Belts/Hoses	●
Emission Sticker	●		

### Interior

Power Door Locks	●	Alarm	●
Back up Camera	●	Navigation/Entertainment System	●
Owners Manual	●	CD/DVD	●
Notes: Missing			
Radio/Speakers	●	Cooled/Heated Seats	●
AC/Heater	●	Trunk Release	●
Tilt Steering Column Functions	●	Parking Brake	●
Dome Light	●	Knobs, Buttons and Other Controls	●
Horn Functions	●	Hood Release	●
Hazard Lights	●	Power Mirrors	●
Power Seats	●	Power Sunroof	●
Seatbelts	●	Power Windows	●
Carpet - Front	●	Warning Lights	●
Headliner Condition	●	Convertible Top Operational	○
Interior Trim	●	Cargo Area Carpet	●
First Aid Kit If Applicable	○	Spare Tire	●
Tailgate Closing Assist	●	Toolkit Complete	○
Carpet - Rear	●		

Date : 18 Jul 2014

Signature : \_\_\_\_\_

V1.3B2B

# Condition Report

Completed by Alliance Inspection Management

2008 GMC Yukon XL Denali

VIN: 1GKFK668081103403

## Vehicle Pictures

Picture Description : **Left Front Corner**



Picture Description : **Other**



Picture Description : **Cargo Area**




Picture Description : **Wheel**



Picture Description : **Other**



Picture Description : **VIN**



# Condition Report

Completed by Alliance Inspection Management

## 2008 GMC Yukon XL Denali

VIN: 1GKFK668081103403

Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Wheel**



Picture Description : **Wheel**



Picture Description : **Other**



# Condition Report

Completed by Alliance Inspection Management

## 2008 GMC Yukon XL Denali

VIN: 1GKFK668081103403

Picture Description : **Other**



Picture Description : **Other**




Picture Description : **Wheel**



Picture Description : **Other**



Picture Description : **Front Interior**



Picture Description : **Other**



# Condition Report

Completed by Alliance Inspection Management

2008 GMC Yukon XL Denali

VIN: 1GKFK668081103403

Picture Description : **Odometer**



Picture Description : **Right Rear Corner**



Picture Description : **Dashboard**



## Condition Report

Completed by Alliance Inspection Management



**2008 GMC Yukon XL Denali**

VIN: 1GKFK668081103403

### Damage Pictures

Picture Description : **No Picture**

