

Condition Report

Completed by Alliance Inspection Management

2010 Porsche Panamera

VIN: WP0AB2A72AL061940



Vehicle Information

Year : 2010
Brand : Porsche
Model : Panamera
Series : S
Body Type : Sedan
Drive Type : AWD
Engine : 4.8L, 8, Gas
Transmission : 7-Speed A/T
Mileage : 27921
Exterior Color : Black
Trim Color : Grey
Trim Type : Leather

Inspection Details

Inspection Date : 29 Jul 2014 11:09 AM
Inspection ID : 508193
Inspector : 3178
Grade : A

Inspection Notes : Vehicles overall condition is consistent with age and mileage. The interior is in good condition for its age and the exterior is in good shape as well. There are a few exceptions on vehicle, see vehicle conditions sections. The interior function all work. Six (6) point undercarriage inspection performed. Engine cradle o.k.

Vehicle Accessories

- A/C
- Aluminum Wheels
- CD Player
- Floor Mats
- Leather Steering Wheel
- Power Door Locks
- Power Windows
- Rear Reading Lamps
- Sun/Moon Roof
- Traction Control
- ABS
- Auxiliary Audio Input
- Climate Control
- Intermittent Wipers
- MP3 Player
- Power Driver Seat
- Premium Sound System
- Rear Spoiler
- Tire Pressure Monitor
- Trip Computer
- AM/FM Stereo
- Bucket Seats
- Cruise Control
- Keyless Start
- Pass-Through Rear Seat
- Power Passenger Seat
- Rear Head Air Bag
- Rearview Monitor
- Tires - Front Performance
- Adjustable Steering Wheel
- CD Changer
- Driver Air Bag
- Leather Seats
- Passenger Air Bag
- Power Steering
- Rear Parking Aid
- Satellite Radio
- Tires - Rear Performance

Tire Information

	Manufacturer	Size	Depth		Manufacturer	Size	Depth
Left Front :	Continental	255/40-19	6/32	Right Front :	Continental	255/40-19	6/32
Left Rear :	Continental	285/40-19	8/32	Right Rear :	Continental	285/40-19	8/32
Spare :	Tire Does Not Exist			*Tire Depth of 5/32 or greater is considered normal			

Vehicle Condition

Wear and Tear

1	Front Bumper Cover	Scratch Light	1" to 2"
2	Front Bumper Cover Bottom edge	Scratch Heavy	GR 12"
3	Windshield	Chipped	< 1/8"
4	Left Rear Door	Scratch Light	1/8" to 1/2"
5	Rear Bumper Cover	Prev Repair	Acceptable

Condition Report

Completed by Alliance Inspection Management

2010 Porsche Panamera

VIN: WP0AB2A72AL061940

Vehicle Inspection Points

Legend: ● Item inspected and is ok ● Item inspected and contains an issue ○ Item is not present or could not be inspected

Exterior

Vehicle Identification Number On Door Jam	●	Vehicle Identification Number On Dashboard	●
Front Lamps	●	Rear Lamps	●
Side Marker	●	Frame / Unibody	●
Roof Rack	○	Door And Side Moldings	●

Notes: See Vehicle Condition Section

Wiper Blades/Arms	●	Check Engine Compartment for Fluid Leaks	●
Check Transmission For Leaks	●	Battery	●
Fluid Levels	●	Belts/Hoses	●
Emission Sticker	●		

Interior

Power Door Locks	●	Alarm	●
Back up Camera	○	Navigation/Entertainment System	●
Owners Manual	●	CD/DVD	●
Radio/Speakers	●	Cooled/Heated Seats	●
AC/Heater	●	Trunk Release	●
Tilt Steering Column Functions	●	Parking Brake	●
Dome Light	●	Knobs, Buttons and Other Controls	●
Horn Functions	●	Hood Release	●
Hazard Lights	●	Power Mirrors	●
Power Seats	●	Power Sunroof	●
Seatbelts	●	Power Windows	●
Carpet - Front	●	Warning Lights	●
Headliner Condition	●	Convertible Top Operational	○
Interior Trim	●	Cargo Area Carpet	●
First Aid Kit If Applicable	○	Spare Tire	○
Tailgate Closing Assist	●	Toolkit Complete	●
Carpet - Rear	●		

Date : 29 Jul 2014

Signature : _____

V1.3B2B

Condition Report


Completed by Alliance Inspection Management

2010 Porsche Panamera

VIN: WP0AB2A72AL061940

Vehicle Pictures

Picture Description : **Other**



Picture Description : **Other**




Picture Description : **Right Rear Corner**



Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Other**



Condition Report

Completed by Alliance Inspection Management

2010 Porsche Panamera

VIN: WPOAB2A72AL061940

Picture Description : **Other**




Picture Description : **Other**



Picture Description : **Other**



Picture Description : **VIN**



Picture Description : **Cargo Area**



Picture Description : **Other**




Condition Report

Completed by Alliance Inspection Management


2010 Porsche Panamera

VIN: WP0AB2A72AL061940

Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Wheel**



Picture Description : **Front Interior**



Picture Description : **Wheel**



Condition Report

Completed by Alliance Inspection Management


2010 Porsche Panamera

VIN: WP0AB2A72AL061940

Picture Description : **Wheel**



Picture Description : **Other**



Picture Description : **Left Front Corner**



Picture Description : **Other**



Picture Description : **Other**



Picture Description : **Dashboard**



Condition Report

Completed by Alliance Inspection Management

2010 Porsche Panamera

VIN: WP0AB2A72AL061940

Picture Description : **Odometer**



Picture Description : **Other**



Picture Description : **Wheel**



Picture Description : **Other**



Condition Report

Completed by Alliance Inspection Management



2010 Porsche Panamera

VIN: WP0AB2A72AL061940

Damage Pictures

Picture Description :

No Picture

