

LATHAM'S COLLISION , INC.

Workfile ID:

6e9490b7

2360 EAST HUNTINGTON DR, FLAGSTAFF, AZ

86004

Phone: (928) 226-1100

FAX: (928) 226-1110

Preliminary Estimate**Customer: SCHWELZER, TYLER****Job Number:**

Written By: DEAN SWANSON

Insured: SCHWELZER, TYLER

Policy #:

Claim #:

Type of Loss:

Date of Loss:

Days to Repair: 0

Point of Impact:

Owner:SCHWELZER, TYLER
1080 W KAIBAB LN
FLAGSTAFF, AZ 86001
(831) 524-3343 Day**Inspection Location:**LATHAM'S COLLISION , INC.
2360 EAST HUNTINGTON DR
FLAGSTAFF, AZ 86004
Repair Facility
(928) 226-1100 Business**Insurance Company:**

STATE FARM INSURANCE COMPANIES

VEHICLE

1989 FORD LTD CROWN VICTORIA 4D SED 8-5.0L-FI WHITE

VIN: 2FABP73F2KX177379

Interior Color:

Mileage In: 138,556

Vehicle Out:

License: 89AC

Exterior Color: WHITE

Mileage Out:

State: AZ

Production Date:

Condition:

Job #:

TRANSMISSIONAutomatic Transmission
Overdrive**SEATS**Cloth Seats
Reclining Seats**STEERING**

Power Steering

BRAKES

Power Brakes

GLASS

Tinted Glass

WHEELS

Deluxe Wheel Covers

RADIO

AM Radio

FM Radio

Stereo

Search/Seek

INTERIORAir Conditioning
Digital Clock
Intermittent Wipers**EXTERIOR**

Power Mirrors

Dual Mirrors

Body Side Moldings

PAINT

Pinstripes/Graphics

Preliminary Estimate

Customer: SCHWELZER, TYLER

Job Number:

1989 FORD LTD CROWN VICTORIA 4D SED 8-5.0L-FI WHITE

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	REAR DOOR						
2	*	Rpr LT Outer panel		0	0.00	<u>7.0</u>	2.2
3		R&I LT Belt w'strip		0	0.00	0.6	0.0
open		Repl LT Side molding w/o overlay	E8AZ5425532A3Z	1	42.17	0.3	0.0
5		R&I LT Lower molding		0	0.00	0.3	0.0
6		R&I LT Handle, outside		0	0.00	0.6	0.0
7		R&I LT Rear door trim w/Crown Victoria		0	0.00	0.4	0.0
8	QUARTER PANEL						
9	*	Rpr LT Quarter panel w/o vinyl		0	0.00	<u>5.0</u>	2.5
10		Overlap Major Adj. Panel		0	0.00	0.0	-0.4
11	*	R&I Front molding		0	0.00	<u>0.3</u>	0.0
12	*	R&I LT Lower molding rear		0	0.00	<u>0.3</u>	0.0
13		R&I LT Belt molding		0	0.00	0.3	0.0
14		R&I LT Wheel opng mldg		0	0.00	0.3	0.0
15	#	Refn ADD FOR JAMB		0	0.00	0.0	0.5
16	REAR BUMPER						
17		R&I R&I rear bumper		0	0.00	0.7	0.0
18	#	CORROSION PROTECTION		1	10.00 T	0.3	0.0
19	#	COVER CAR		1	6.00	0.3	0.0
20	#	HAZARDOUS WASTE DISPOSAL		1	5.00 X	0.0	0.0
21	#	****OVER THRESHOLD*****		1	0.00	0.0	0.0
SUBTOTALS					63.17	16.7	4.8

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			48.17
Body Labor	16.7 hrs @	\$ 56.00 /hr	935.20
Paint Labor	4.8 hrs @	\$ 56.00 /hr	268.80
Paint Supplies	4.8 hrs @	\$ 35.00 /hr	168.00
Miscellaneous			15.00
Subtotal			1,435.17
Sales Tax	\$ 226.17 @	8.9510 %	20.24
Grand Total			1,455.41
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			1,455.41

Preliminary Estimate

Customer: SCHWELZER, TYLER

Job Number:

1989 FORD LTD CROWN VICTORIA 4D SED 8-5.0L-FI WHITE

The items herein before or attached are an estimate based on our inspection and does not cover any additional parts or labor which may be required after work has been opened up. Occasionally after work has been started, worn or damaged parts are discovered which were not evident on the first inspection. Because of this, the prices listed herein or attached are not guaranteed, and are for immediate acceptance only. I hereby authorize the described repair work to be done, along with the necessary material, and hereby grant you and/ or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/ or inspection. An express mechanic's lien is hereby acknowledged on the herein described vehicle to secure the amount of repairs thereto.

We are not responsible for loss or damage to vehicle or articles left in case of fire, theft, or any other cause beyond our control.

Signature_____date_____

FOR YOUR PROTECTION ARIZONA LAW REQUIRES THE FOLLOWING STATEMENT TO APPEAR ON THIS FORM. ANY PERSON WHO KNOWINGLY PRESENTS A FALSE OR FRAUDULENT CLAIM FOR PAYMENT OF A LOSS IS SUBJECT TO CRIMINAL AND CIVIL PENALTIES.